SOUTHLANDS METROPOLITAN DISTRICT NO. 1

141 Union Boulevard, Suite 150 Lakewood, Colorado 80228-1898 Tel: (303) 987-0835 Fax: (303) 987-2032 Website: https://southlandsmd1.colorado.gov/

NOTICE OF REGULAR MEETING AND AGENDA

Board of Directors: Martin Liles Joyce Rocha April Elliott VACANT VACANT Office: President Secretary Treasurer Term/Expires: 2023/May 2023 2025/May 2025 2025/May 2025 2025/May 2023 2023/May 2023

DATE:	August 16, 2022
TIME:	9:30 a.m.
PLACE:	Southlands Shopping Center
	Management Office
	6155 South Main Street, Suite 260
	Aurora, Colorado 80016

I. ADMINISTRATIVE MATTERS

- A. Present Disclosures of Potential Conflicts of Interest.
- B. Approve Agenda; confirm location of the meeting and posting of meeting notice.
- C. Review and approve Minutes of the June 28, 2022 Special Meeting (enclosure).

II. PUBLIC COMMENTS

- A. Members of the public may express their views to the Board on matters that affect the District. Comments will be limited to three (3) minutes.
- III. CONSENT AGENDA These items are considered to be routine and will be approved and/or ratified by one motion. There will be no separate discussion of these items unless a Board member so requests, in which event, the item will be removed from the Consent Agenda and considered in the Regular Agenda.
 - Ratify approval of proposal from MR/Westco Inc. for paver replacement (enclosure).

Southlands Metropolitan District No. 1 August 16, 2022 Agenda Page 2

- Ratify approval of First Amendment to Independent Contractor Agreement between the District and Common Area Maintenance Services, LLC street sweeping (enclosure).
- Ratify approval of the reimbursement to Shannon Worrell for damaged windshield (enclosure).

IV. FINANCIAL MATTERS

A. Review and ratify approval of the payment of claims for the periods ending as follows (enclosure):

Fund	Period Ending July 31, 2022
General	\$ 108,665.07
Debt Service	\$ -0-
Capital Projects	\$ 118,970.93
Total Claims	\$ 227,636.00

B. Review and accept unaudited financial statements for the period ending June 30, 2022 and accept Cash Position Schedule, dated June 30, 2022, updated August 3, 2022 and Operations Fee Report (enclosure).

V. LEGAL MATTERS

- A. Discuss status of a License Agreement concerning the E-470 monument signs.
- B. Discuss and consider approval of Resolution Regarding Issuance of Advertising Events, Special Events, Street Closure Permit and Signage.

VI. OPERATIONS AND MAINTENANCE

A. Discuss status of the Special Events Permit from M&J Wilkow.

- B. Review and consider approval of a proposals for tree and shrub replacements:
 - 1. Tree replacements in the Town Square from Keesen Landscape Management Inc., in the amount of \$3,904.99 (enclosure).
 - 2. Plant replacements on Main Street from Keesen Landscape Management Inc., in the amount of \$9,276.73 (enclosure).
 - 3. Shrub replacements on Main Street from Longhill Contracting, in the amount of \$2,617.75 (enclosure).
- C. Review and consider approval of a proposal from Full Spectrum Lighting, Inc. for the conversion of the lights to LED (enclosure).
- D. Review and consider approval of a proposals for striping the District's roads and parking spaces (enclosures).
- E. Discuss 2022/2023 Independent Contractor Agreements for 2023 Maintenance Services:
 - 1. Holiday Lighting.
 - 2. Security Services (enclosure).
 - 3. Snow Removal Services.
 - 4. Landscape Maintenance Services.
 - 5. Floral Program.
 - 6. Common Area Cleaning.

Southlands Metropolitan District No. 1 August 16, 2022 Agenda Page 4

- 7. Site Lighting Services.
- 8. Locate Services (enclosure).
- 9. Tree Care Services.
- 10. Street Sweeping Services
- F. Review and discuss retaining wall inspection report (enclosures).
- G. Discuss scheduling a demo with MyAssetMap for mapping and tracking improvements.

VII. CAPITAL IMPROVEMENTS

- A. Discuss status of the installation of the Cub Hub sign.
- B. Discuss status of the Median Landscape Renovation Project.
 - 1. Review and ratify approval of the revised Change Order No. 2 from Keesen Landscape Management Inc. (enclosure).
- C. Discuss capital improvement projects for 2023.

VIII. OTHER MATTERS

A. _____

IX. ADJOURNMENT <u>THE NEXT REGULAR MEETING IS SCHEDULED FOR</u> OCTOBER 18, 2022

RECORD OF PROCEEDINGS

<u>0924.0006</u>

MINUTES OF A SPECIAL MEETING OF THE BOARD OF DIRECTORS OF THE SOUTHLANDS METROPOLITAN DISTRICT NO. 1 HELD JUNE 28, 2022

A Special Meeting of the Board of Directors (referred to hereafter as "Board") of the Southlands Metropolitan District No. 1 (referred to hereafter as "District") was convened on Tuesday, the 28th day of June, 2022, at 9:30 a.m. at the Southlands Shopping Center, Management Office, 6155 South Main Street, Suite 260, Aurora, Colorado 80016. The meeting was open to the public.

ATTENDANCE

Directors In Attendance Were:

Martin Liles Joyce Rocha April Elliott

Also In Attendance Were:

Ann E. Finn; Special District Management Services, Inc.

Erin Stutz, Esq.; White Bear Ankele Tanaka & Waldron P.C.

Thuy Dam; CliftonLarsonAllen, LLP

DISCLOSURE OF POTENTIAL CONFLICTS OF INTEREST Disclosure of Potential Conflicts of Interest: Ms. Finn noted that a quorum was present. Attorney Stutz reported that disclosures for those Directors that provided White Bear Ankele Tanaka & Waldron with notice of potential or existing conflicts of interest were filed with the Secretary of State's Office and the Board at least 72 hours prior to the meeting, in accordance with Colorado law, and those disclosures were acknowledged by the Board. Attorney Stutz asked the Board whether members of the Board had any additional disclosures of potential or existing conflicts of interest with regard to any matters scheduled for discussion at the meeting. No additional disclosures were noted. The participation of the members present was necessary to obtain a quorum or to otherwise enable the Board to act.

<u>ADMINISTRATIVE</u> <u>MATTERS</u>

<u>Agenda</u>: Ms. Finn noted she had distributed for the Board's review and approval a proposed Agenda for the District's Special Meeting.

Following discussion, upon motion duly made by Director Rocha, seconded by Director Elliott and, upon vote, unanimously carried, the Agenda was approved, as amended.

<u>Minutes</u>: The Board reviewed the Minutes of the April 5, 2022 and May 10, 2022 Special Meetings.

Following discussion, upon motion duly made by Director Elliott, seconded by Director Rocha and, upon vote, unanimously carried, the Minutes of the April 5, 2022 and May 10, 2022 Special Meetings were approved, as presented.

<u>2022</u> SDA Conference: Ms. Finn discussed the SDA Conference with the Board, and noted the information concerning the details of the conference will be emailed to them once the information is available.

<u>PUBLIC COMMENTS</u> There were no public comments at this time.

<u>CONSENT AGENDA</u> The Board considered the following actions:

- Ratify approval of proposal from Full Spectrum Lighting, Inc. to replace the failed pumps in the pump room for the fountain.
- Ratify approval of proposal from Keesen Landscape Management, Inc. for the addition of weed barrier to all islands.
- Ratify approval of proposal from Keesen Landscape Management, Inc. for additional flower baskets.

Following discussion, upon motion duly made by Director Elliott, seconded by Director Liles and, upon vote, unanimously carried, the Board approved and/or ratified approval of the Consent Agenda items.

<u>FINANCIAL</u> <u>MATTERS</u>

<u>Claims</u>: The Board considered ratifying approval of the payment of claims for the period ending as follows:

Fund	Period Ending Feb. 28, 2022	Period Ending March 31, 2022	Period Ending May 31, 2022	
General	\$ 187,528.69	\$ 52,432.88	\$ 118,240.09	\$ 369,668.60
Debt Service	\$ -0-	\$ -0-	\$ -0-	\$ -0-
Capital Projects	\$ 745.69	\$ 3,295.58	\$ 4,871.94	\$ 586.25
Total Claims	\$ 188,274.38	\$ 55,728.46	\$ 123,112.03	\$ 370,254.86

Fund	Special Payment May 25, 2022	Period Ending June 30, 2022
General	\$ 1,524.38	\$ 82,974.85
Debt Service	\$ -0-	\$ -0-
Capital Projects	\$ -0-	\$ 2,865.00
Total Claims	\$ 1,524.38	\$ 85,839.85

Following review, upon motion duly made by Director Elliott seconded by Director Rocha and, upon vote, unanimously carried, the Board ratified approval of claims, as amended to hold \$40,000 from the Keesen floral invoice #185366 for \$164,250.42 for watering hanging baskets.

Financial Statements: Ms. Dam reviewed with the Board the unaudited financial statements of the District for the period ending April 30, 2022, Cash Position Schedule, dated April 30, 2022, updated June 14, 2022 and Operations Fee Report.

Following discussion, upon motion duly made by Director Elliott, seconded by Director Rocha and, upon vote, unanimously carried, the Board accepted the unaudited financial statements of the District for the period ending April 30, 2022, the Cash Position Schedule, dated April 30, 2022, updated June 14, 2022 and Operations Fee Report.

<u>2021 Audit</u>: Ms. Dam reviewed the 2021 draft Audited Financial Statements with the Board.

Following review and discussion, upon motion duly made by Director Elliott, seconded by Director Rocha and, upon vote, unanimously carried, the Board approved the 2021 Audited Financial Statements and authorized execution of the Representations Letter, subject to final review by legal counsel and receipt of an unmodified opinion letter from the auditor.

LEGAL MATTERS License Agreement: Attorney Stutz reported to the Board that Attorney Waldron is working with Alberta Development Partners, LLC on the License Agreement concerning the E-470 monument signs.

OPERATIONS AND MAINTENANCESpecial Events Permit from M&J Wilkow: Director Rocha reported to the Board on the status of the 2022 Special Events Permit from M&J Wilkow. She noted the Certificate of Insurance will be submitted with the permit once available.

Irrigation Supplies: The Board entered into discussion regarding cost sharing irrigation supplies between the District and M&J Wilkow. Ms. Finn recommended the District share the cost of irrigation supplies with M&J Wilkow on a percentage basis. Following discussion, the Board agreed to have the District back charge M&J Wilkow \$2,000 per year starting in 2023 for irrigation supplies.

Independent Contractor Agreement between Collins Engineers of Illinois, Inc. d/b/a Collins Engineering, Inc. and the District for Retaining Wall Inspections: The Board reviewed an Independent Contractor Agreement between Collins Engineers of Illinois, Inc. d/b/a Collins Engineering, Inc. and the District for retaining wall inspections.

Following review and discussion, upon motion duly made by Director Liles, seconded by Director Elliott and, upon vote, unanimously carried, the Board approved the Independent Contractor Agreement between Collins Engineers of Illinois, Inc. d/b/a Collins Engineering, Inc. and the District for retaining wall inspections.

Proposal from Keesen Landscape Management, Inc. for Tree and Shrub Replacements: The Board deferred discussion.

Proposal from CAM Services for Increasing Street Sweeping Services: The Board entered into discussion regarding a proposal from CAM Services for increasing street sweeping services.

Following review and discussion, upon motion duly made by Director Liles, seconded by Director Rocha and, upon vote, unanimously carried, the Board approved the proposal from CAM Services for increasing street sweeping services from two to three times per week, for an amount of \$1,365 per month.

Tree Replacement Proposal: Director Liles noted for the Board that he approved a tree replacement proposal for three (3) trees located in the plaza, for the amount of \$3,900. He also noted he purchased mulch for the flower beds, for the amount of \$5,000.

<u>CAPITAL</u> <u>IMPROVEMENTS</u>

<u>Cub Hub Sign</u>: Director Liles provided an update regarding the status of installation of the Cub Hub sign. He noted a preconstruction meeting is scheduled for Thursday, June 30, 2022.

<u>Median Landscape Renovation Project ("Project")</u>: The Board reviewed Change Order No. 2 to the Project Manual for the Median Landscape Renovation Project.

Following review and discussion, upon motion duly made by Director Elliott, seconded by Director Rocha and, upon vote, unanimously carried, the Board authorized Director Liles to negotiate Change Order No. 2 with Keesen Landscape Management, Inc., for an amount not to exceed \$50,000.

RECORD OF PROCEEDINGS

There were no other matters. **OTHER MATTERS**

There being no further business to come before the Board at this time, upon **ADJOURNMENT** motion duly made by Director Liles, seconded by Director Rocha and, upon vote, unanimously carried, the meeting was adjourned.

Respectfully submitted,

By: ______ Secretary for the Meeting

MR/Westco Inc.

Denver, CO 80237

PROPOSAL

Date	Estimate #
7/18/2022	12501

Name / Address

Southlands Property # 0830 6155 South Main Street Aurora, Colorado 80016

Property

Southlands 6235 S. Main St. Aurora CO 80016

ltem	Description	Qty	Rate	Total
	07/18/2022 - Proposal for Mr. Quincy Hudspeth - Paver Replacement			
26 Landsc	Demolish the nine (9) damaged pavers in the designated area Install nine (9) new pavers from management stock Five (5) of the pavers will be custom cut to match the existing Adhere the pavers as necessary Apply a polymeric paver joint sand NOTE: Southland's Management will be providing the replacement pavers		1,443.00	1443.0

Phone #	Fax #	E-mail		Total	\$1,443.00
(303) 708-1833	(303) 756-0218	Scheduling@mrwestco.com			

FIRST AMENDMENT TO INDEPENDENT CONTRACTOR AGREEMENT (STREET SWEEPING)

This FIRST AMENDMENT TO INDEPENDENT CONTRACTOR AGREEMENT, including any and all exhibits attached hereto (the "**First Amendment**"), is entered into as of the 18th day of July, 2022, effective the 1st day of July, 2022, by and between SOUTHLANDS METROPOLITAN DISTRICT NO. 1, a quasi-municipal corporation and political subdivision of the State of Colorado (the "**District**"), and COMMON AREA MAINTENANCE SERVICES, LLC, a Colorado limited liability company (the "**Contractor**"). The District and the Contractor are referred to herein as a "**Party**" and collectively as the "**Parties**."

RECITALS

WHEREAS, the Parties entered into that certain *Independent Contractor Agreement* (*Street Sweeping*) dated January 1, 2022 (the "**Agreement**"); and

WHEREAS, the Agreement sets forth the Scope of Services to be completed and the Compensation Schedule therefore; and

WHEREAS, the Parties desire the Contractor to perform additional services not initially contemplated in the Agreement.

NOW, THEREFORE, in consideration of the mutual covenants and stipulations set forth herein, and for other good and valuable consideration, the receipt and sufficiency of which are hereby acknowledged, the Parties hereto agree as follows:

TERMS AND CONDITIONS

1. <u>AMENDMENT TO SCOPE OF SERVICES/COMPENSATION SCHEDULE</u>. The Parties hereby amend and restate in its entirety the Scope of Services/Compensation Schedule set forth in Exhibit A of the Agreement with the Scope of Services/Compensation Schedule set forth in **Exhibit A** attached to hereto and incorporated herein by this reference. This First Amendment shall be effective as of July 1, 2022.

2. <u>PRIOR PROVISIONS EFFECTIVE</u>. Except as specially amended hereby, all the terms and provisions of the Agreement shall remain in full force and effect.

3. <u>COUNTERPART EXECUTION</u>. This First Amendment may be executed in several counterparts, each of which may be deemed an original, but all of which together shall constitute one and the same instrument. Executed copies of this First Amendment may be delivered by facsimile or email of a PDF document, and, upon receipt, shall be deemed originals and binding upon the signatories to this First Amendment.

[Signature Pages Follow.]

IN WITNESS WHEREOF, the Parties have executed this First Amendment on the date first above written. By the signature of its representative below, each Party affirms that it has taken all necessary action to authorize said representative to execute this First Amendment.

DISTRICT:

SOUTHLANDS METROPOLITAN DISTRICT NO. 1, a quasi-municipal corporation and political subdivision of the State of Colorado

Officer of the District

ATTEST:

APPROVED AS TO FORM:

WHITE BEAR ANKELE TANAKA & WALDRON Attorneys at Law

General Counsel for the District

CONTRACTOR: COMMON AREA MAINTENANCE SERVICES, LLC, a Colorado limited liability company

Printed Name

Title

EXHIBIT A

SCOPE OF SERVICES/COMPENSATION SCHEDULE



PROPOSAL SUBMITTED TO: ADDRESS:	Special District Management Services, Inc. Southlands Metropolitan District No. 1 141 Union Boulevard, Ste 150 Lakewood, CO 80228
CONTACT:	Ann Finn
PHONE:	303-987-0835
EMAIL:	afinn@sdmsi.com
DATE:	Wednesday, June 22, 2022
JOB NAME AND ADDRESS:	Southlands Shopping Center / Metro District
	(E. Smoky Hill & Main St., Aurora, CO 80016) July 1, 2022 – December 31, 2022

Power Sweeping

Sweep and detail (power blow) drive lanes, inside and outside curb lines and all corners.

\$1,365 /mth

Power Sweeping includes the following;

- 3x /week service between 11:pm 7:am
 - Tuesday night into Wednesday morning
 - Friday night into Saturday morning
 - o Saturday night into Sunday morning
- All labor and equipment necessary to complete the above specification.
- Equipment used will be capable of removing all trash, debris, and sand by means of air vacuum with dust control.
- All areas not accessible to mechanical equipment will be blown free of trash and debris by hand held blowers.
- All trash, debris, and sand will be disposed of offsite unless otherwise agreed upon.
 no dumping available onsite
- Service schedule to be agreed upon by both parties.
- Additional work will be at an additional cost.

Southlands Metropolitan District Roads to include;

- East Orchard Rd.
- Prospect Avenue
- South Central Street
- South Southlands Parkway
 - o (Includes Main Street Shops and Parking (South Main Street & East Commons Avenue).
- Refer to map (attached)

This pricing assumes contracts with both the Power Center and Town Center portions of Southlands, as well as, Southlands Metro District.

Page 1 of 2

initial _____

Upon signing above, I issue my personal guarantee of payment, which will be remitted upon invoice. Additional charges of 3.5% for credit card usage. All invoices are due and payable upon receipt. In the event the amount of an invoice is not paid within 30 days from the date of the invoice, the account shall be deemed to be in default and Contractor reserves the right to cease any further work until the account is brought current. Any invoice not paid within 30 days from the date of the invoice shall accrue interest at the maximum lawful rate of 1-1/2% per month, not to exceed 19% per annum. Owner/Customer agrees to indemnify the Contractor harmless from any costs or expenses incurred in the collection of the defaulted account, or in any part thereof, including all reasonable attorney fees, court cost, etc. All services in Denver County subject to Denver County Tax





Page 2 of 2


initial _____

Upon signing above, I issue my personal guarantee of payment, which will be remitted upon invoice. Additional charges of 3.5% for credit card usage. All invoices are due and payable upon receipt. In the event the amount of an invoice is not paid within 30 days from the date of the invoice, the account shall be deemed to be in default and Contractor reserves the right to cease any further work until the account is brought current. Any invoice not paid within 30 days from the date of the invoice shall accrue interest at the maximum lawful rate of 1-1/2% per month, not to exceed 19% per annum. Owner/Customer agrees to indemnify the Contractor harmless from any costs or expenses incurred in the collection of the defaulted account, or in any part thereof, including all reasonable attorney fees, court cost, etc. All services in Denver County subject to Denver County Tax

Brooke Cowdrey – 303-265-1018 Cell – <u>brooke@camcolorado.com</u> 2525 W. 64th Avenue • Denver Colorado 80221 • 303 295-2424 • 303 295-2436 Fax • www.camcolorado.com Power Sweeping • Snow Removal • Temporary Fence • Property Maintenance • Power Washing • Tenant Finish • Day Porter Power Scrubbing • Building Maintenance • Construction Clean-Up • Debris Removal • Construction Demo From: Shannon Irons <shanirons822@gmail.com> Sent: Wednesday, August 03, 2022 11:05 AM To: Ann Finn <afinn@sdmsi.com> Subject: httpssafelite-prod-mrmdocuments.s3.amazonaws.com1C7F3Receipt-2150-384058-2022-08-03-12-49-31.pdfAWSAccessKeyId=AKIA2CC6ER6

This is the receipt for my windshield. I drive my car for my job as a home IV therapy nurse and was unable to work since this occurred. I was hoping that would be taken into consideration as well. I missed 6 calls and my average pay per call is \$125. I appreciate any assistance I can get.

Thank you Shannon Worrell



Southlands Metropolitan District No. 1 July-22

Vendor	Invoice #	Date	Due Date	An	nount	Expense Account	Account Number
Allied Universal	12927297	6/30/2022	7/30/2022	\$	4,663.36	Security	117806
Brody Chemical	INV14701	6/30/2022	7/30/2022	\$	104.99	Repairs and maintenance	117582
City of Aurora	151228 June22	6/30/2022	6/30/2022	\$	1,107.36	Utilities	117701
City of Aurora	150518 June22	6/30/2022	6/30/2022	\$	1,488.01	Utilities	117701
City of Aurora	146452 June22	6/30/2022	6/30/2022	\$	1,490.87	Utilities	117701
City of Aurora	152426 June22	6/30/2022	6/30/2022	\$	4,467.77	Utilities	117701
City of Aurora	142090 June22	6/30/2022	6/30/2022	\$	2,366.89	Utilities	117701
City of Aurora	146396 June22	6/30/2022	6/30/2022	\$	398.40	Utilities	117701
City of Aurora	151226 June22	6/30/2022	6/30/2022	\$	592.62	Utilities	117701
City of Aurora	151230 June22	6/30/2022	6/30/2022	\$	1,278.94	Utilities	117701
City of Aurora	146368 June22	6/30/2022	6/30/2022	\$	8,983.91	Utilities	117701
CliftonLarsonAllen LLP	3315703	5/31/2022	5/31/2022	\$	6,266.03	Accounting	107000
Colorado Steel Inc	5260	6/15/2022	6/15/2022	\$	3,468.00	Repairs and maintenance	117582
Common Area Maintenance Services	M07012463	7/1/2022	7/1/2022	\$	1,365.00	Street sweeping	117808
DBC Irrigation Supply	S4662757.001	7/1/2022	7/1/2022	\$	580.37	Landscape maintenance & irrigation repair	117585
Full Spectrum Lighting, Inc	30146	6/20/2022	6/20/2022	\$	4,473.00	Street lighting/ striping	117855
Full Spectrum Lighting, Inc	30142	6/20/2022	6/20/2022	\$	640.00	Street lighting/ striping	117855
Keesen Landscape Management, Inc.	CEN 190793	7/1/2022	7/31/2022	\$	16,235.00	Landscape maintenance & irrigation repair	117585
Keesen Landscape Management, Inc.	CEN 189659	6/7/2022	7/7/2022	\$	960.00	Landscape maintenance & irrigation repair	117585
Keesen Landscape Management, Inc.	CEN 189985	6/20/2022	7/20/2022	\$	115.00	Landscape maintenance & irrigation repair	117585
Keesen Landscape Management, Inc.	CEN 192186	7/1/2022	7/31/2022	\$	4,904.78	Landscape maintenance & irrigation repair	117585
Keesen Landscape Management, Inc.	CEN 189591	6/8/2022	7/8/2022	\$	2,053.75	Floral	117801
Keesen Landscape Management, Inc.	CEN 192026	6/30/2022	7/30/2022	\$1	.16,612.50	Medians	307863
Keesen Landscape Management, Inc.	CEN 191723	6/20/2022	7/20/2022	\$	1,985.16	Landscape maintenance & irrigation repair	117585
M & J Wilkow Properties, LLC	28286	7/31/2022	7/31/2022	\$	9,616.33	Property maintenance	117804
Millard Mall Services	82188	6/16/2022	7/16/2022	\$	15,204.25	Monthly cleaning	117802
Special District Management Services, Inc.	PM 06/2022	6/30/2022	6/30/2022	\$	3,000.00	Property management	117805
Special District Management Services, Inc.	DM 06/2022	6/30/2022	6/30/2022	\$	190.00	Medians	307863
Special District Management Services, Inc.	DM 06/2022	6/30/2022	6/30/2022	\$	4,164.92	District management	107440
The Architerra Group, Inc.	7297	7/5/2022	8/4/2022	\$	1,802.50	Medians	307863
Utility Notification Center of Colorado	222061414	6/30/2022	6/30/2022	\$	9.10	Repairs and maintenance	117582
White, Bear & Ankele PC	22972	6/30/2022	6/30/2022	\$	166.05	Election expense	107581
White, Bear & Ankele PC	22972	6/30/2022	6/30/2022	\$	365.93	Medians	307863
White, Bear & Ankele PC	22972	6/30/2022	6/30/2022	\$	2,888.87	Legal services	107460
Xcel Energy	788101957	7/15/2022	7/15/2022	\$	3,626.34	Utilities	117701

\$227,636.00

Southlands Metropolitan District No. 1 July-22

Disbursements		General		Debt	Capital	Totals		
		82,863.96			\$ 118,970.93	\$	201,834.89	
Xcel - Auto Pay	\$	3,626.34	\$	-	\$ -	\$	3,626.34	
Aurora Water - Auto Pay	\$	22,174.77	\$	-	\$ -	\$	22,174.77	
Total Disbursements from Checking Acc	\$	108,665.07	\$	-	\$ 118,970.93	\$	227,636.00	

SOUTHLANDS METROPOLITAN DISTRICT NO.1

FINANCIAL STATEMENTS

JUNE 30, 2022

SOUTHLANDS METROPOLITAN DISTRICT NO.1 BALANCE SHEET - GOVERNMENTAL FUNDS

JUNE 30, 2022

	General	c	General Operations Fee	De	ebt Service	Capital Projects	Total
ASSETS							
Cash - Checking	\$ 22,455	\$	610,843	\$	-	\$ 2,865	\$ 636,163
Colotrust	1,305,614		822,877		517	-	2,129,008
UMB Series 2017 A-1 Bond Fund	-		-		1,826,339	-	1,826,339
UMB Series 2017 A-2 Bond Fund	-		-		341,853	-	341,853
UMB Series 2017 A-1 Reserve Fund	-		-		1,688,166	-	1,688,166
UMB Series 2017 A-2 Reserve Fund	-		-		149,798	-	149,798
General Operations Fee receivable	-		132,623		-	-	132,623
Due from other fund	-		-		-	117,168	117,168
Receivable from County Treasurer	33,615		-		232,483	-	266,098
TOTAL ASSETS	\$ 1,361,684	\$	1,566,343	\$	4,239,156	\$ 120,033	\$ 7,287,216
LIABILITIES AND FUND BALANCES							
CURRENT LIABILITIES							
Accounts payable	\$ 34,496	\$	307,040	\$	-	\$ 120,033	\$ 461,569
Due to other funds	117,168		-		-	-	117,168
Unearned General Operations Fee	 -		4,665		-	 -	 4,665
Total Liabilities	 151,664		311,705			 120,033	 583,402
FUND BALANCES							
Total Fund Balances	 1,210,020		1,254,638		4,239,156	 -	 6,703,814
TOTAL LIABILITIES AND FUND BALANCES	\$ 1,361,684	\$	1,566,343	\$	4,239,156	\$ 120,033	\$ 7,287,216

SOUTHLANDS METROPOLITAN DISTRICT NO.1 STATEMENT OF REVENUES, EXPENDITURES AND CHANGES IN FUND BALANCES - BUDGET AND ACTUAL FOR THE SIX MONTHS ENDED JUNE 30, 2022

GENERAL FUND

	Annual Budget		Year to Date Actual		Variance
REVENUES					
Interest income	\$	500	\$	2,585	\$ 2,085
Permits and fees		5,000		-	(5,000)
Property taxes		507,927		497,894	(10,033)
Specific ownership tax		35,555		17,675	(17,880)
TOTAL REVENUES		548,982		518,154	 (30,828)
EXPENDITURES					
Accounting		57,000		31,079	25,921
Auditing		6,000		-	6,000
Billing services		13,000		5,573	7,427
Contingency		9,381		-	9,381
County Treasurer's fee		7,619		7,497	122
Directors' fees		4,000		900	3,100
District management		68,000		24,375	43,625
Dues and licenses		2,000		545	1,455
Election expense		3,000		1,805	1,195
Insurance and bonds		45,000		36,928	8,072
Legal services		50,000		21,430	28,570
Miscellaneous		5,000		368	4,632
Public Events		50,000		-	 50,000
TOTAL EXPENDITURES		320,000		130,500	 189,500
EXCESS OF REVENUES OVER (UNDER) EXPENDITURES		228,982		387,654	158,672
OTHER FINANCING SOURCES (USES)					
Transfers to other fund		(700,000)		(131,266)	 568,734
TOTAL OTHER FINANCING SOURCES (USES)		(700,000)		(131,266)	 568,734
NET CHANGE IN FUND BALANCES		(471,018)		256,388	727,406
FUND BALANCES - BEGINNING		941,998		953,633	 11,635
FUND BALANCES - ENDING	\$	470,980	\$	1,210,021	\$ 739,041

SOUTHLANDS METROPOLITAN DISTRICT NO.1 STATEMENT OF REVENUES, EXPENDITURES AND CHANGES IN FUND BALANCES - BUDGET AND ACTUAL FOR THE SIX MONTHS ENDED JUNE 30, 2022

GENERAL OPERATIONS FEE FUND

	Annual Budget	Y	ear to Date Actual	Variance
REVENUES				
General operations fee	\$ 2,103,000	\$	1,051,500	\$ (1,051,500)
General operations fee - penalty and other	2,000		10,345	8,345
General operations fee - vacant lots	25,000		24,961	(39)
Interest income	1,000		2,074	1,074
Reimbursed expenditures	-		1,600	1,600
TOTAL REVENUES	 2,131,000		1,090,480	 (1,040,520)
EXPENDITURES				
Floral	190,000		168,242	21,758
Holiday decor	115,000		-	115,000
Landscape maintenance & irrigation repair	250,000		101,486	148,514
Monthly cleaning	230,000		90,373	139,627
Pest control	10,000		-	10,000
Property maintenance	120,000		57,778	62,222
Property management	40,000		18,032	21,968
Repairs and maintenance	380,000		36,159	343,841
Security	75,000		30,189	44,811
Signage	100,000		13,007	86,993
Snow removal	350,000		178,159	171,841
Street lighting/ striping	75,000		28,115	46,885
Street repairs/sidewalk	45,000			45,000
Street sweeping	15,000		7,755	7,245
Traffic signals maintenance	35,000		30,229	4,771
Utilities	 180,000		54,428	 125,572
TOTAL EXPENDITURES	 2,210,000		813,952	 1,396,048
NET CHANGE IN FUND BALANCES	(79,000)		276,528	355,528
FUND BALANCES - BEGINNING	 729,000		978,108	 249,108
FUND BALANCES - ENDING	\$ 650,000	\$	1,254,636	\$ 604,636

SUPPLEMENTARY INFORMATION

SOUTHLANDS METROPOLITAN DISTRICT NO.1 SCHEDULE OF REVENUES, EXPENDITURES AND CHANGES IN FUND BALANCES - BUDGET AND ACTUAL FOR THE SIX MONTHS ENDED JUNE 30, 2022

DEBT SERVICE FUND

	Annual Budget	Y	ear to Date Actual	Variance
REVENUES				
Interest income	\$ 700	\$	1,034	\$ 334
Property taxes	2,873,318		2,818,521	(54,797)
Specific ownership tax	201,132		99,591	(101,541)
TOTAL REVENUES	 3,075,150		2,919,146	 (156,004)
EXPENDITURES				
Bond interest - Series 2017 A-1	2,073,200		1,036,600	1,036,600
Bond interest - Series 2017 A-2	183,275		91,638	91,637
Bond principal - Series 2017 A-1	590,000		-	590,000
Bond principal - Series 2017 A-2	50,000		-	50,000
Contingency	9,425		-	9,425
County Treasurer's fee	43,100		42,436	664
Paying agent fees	 6,000		-	 6,000
TOTAL EXPENDITURES	 2,955,000		1,170,674	 1,784,326
NET CHANGE IN FUND BALANCES	120,150		1,748,472	1,628,322
FUND BALANCES - BEGINNING	 2,503,308		2,490,684	 (12,624)
FUND BALANCES - ENDING	\$ 2,623,458	\$	4,239,156	\$ 1,615,698

SOUTHLANDS METROPOLITAN DISTRICT NO.1 SCHEDULE OF REVENUES, EXPENDITURES AND CHANGES IN FUND BALANCES - BUDGET AND ACTUAL FOR THE SIX MONTHS ENDED JUNE 30, 2022

CAPITAL PROJECTS FUND

	Annual Budget	Year to Date Actual	Variance
REVENUES	U		
TOTAL REVENUES			
EXPENDITURES			
Medians	400,000	131,266	268,734
Signage	300,000	-	300,000
TOTAL EXPENDITURES	700,000	131,266	568,734
EXCESS OF REVENUES OVER (UNDER) EXPENDITURES	(700,000)	(131,266)	568,734
OTHER FINANCING SOURCES (USES)			
Transfers from other funds	700,000	131,266	(568,734)
TOTAL OTHER FINANCING SOURCES (USES)	700,000	131,266	(568,734)
NET CHANGE IN FUND BALANCES	-	-	-
FUND BALANCES - BEGINNING			
FUND BALANCES - ENDING	<u>\$</u>	<u> </u>	<u> </u>

Services Provided

The District was organized by court order dated December 3, 2002, to provide financing for the design, acquisition, construction and installation of essential public-purpose facilities such as water, streets, traffic and safety controls, parks, open space and recreation, and sewer and drainage facilities, and the operation and maintenance of the District. The District's service area is located entirely in Arapahoe County, Colorado in the City of Aurora.

The District operates under the Service Plan as approved by the City of Aurora.

On November 5, 2002, the electorate authorized general obligation debt in the amount of \$63,000,000, refunding debt of \$49,000,000 and \$1,000,000 debt for operating expenditures. Debt is subject to the terms of the Service Plan. On November 5, 2002, the electorate also approved the removal of limitations imposed by the TABOR Amendment and any other law that purports to limit the District's revenue or expenditures and a \$130,000 annual property tax increase for operations.

On November 4, 2008, the electorate approved general obligation debt in the amount of \$440,000,000 for District improvements, \$40,000,000 for the purpose of refunding, refinancing or defeasing any of the District's debt, \$40,000,000 in multi-year intergovernmental agreements, \$40,000,000 in multi-year agreements with a regional authority and \$40,000,000 in other multi-year financial obligations. Additionally, on November 4, 2008, the electorate approved \$5,000,000 annually for the District's administrative and operating costs from property taxes as well as from fees. The electorate also approved \$5,000,000 in additional property taxes for intergovernmental agreements, \$5,000,000 in additional property taxes for private contracts. The electorate also authorized the District to collect, retain and spend the full amount of taxes and fees without regard to the limitation of TABOR.

The First Amendment to the Service Plan, approved by the City of Aurora on July 16, 2007, authorized the District to impose an unlimited mill levy on taxable property within its boundaries as a primary source of revenue for repayment of debt service and for operations and maintenance.

Pursuant to the District's First Amendment to the Service Plan as approved by the City of Aurora on July 16, 2007, the amount of debt that can be issued is \$60,000,000. On January 11, 2016, the City Council approved the Second Amendment to the Service Plan which increases the debt issuance limitation to \$125,000,000.

The District has no employees and all administrative functions are contracted.

The District prepares its budget on the modified accrual basis of accounting in accordance with the requirements of Colorado Revised Statues C.R.S. 29-1-105 using its best estimates as of the date of the budget hearing. These estimates are based on expected conditions and its expected course of actions. The assumptions disclosed herein are those that the District believes are significant to the budget. There will usually be differences between the budget and actual results, because events and circumstances frequently do not occur as expected, and those differences may be material.

Revenues

Property Taxes

Property taxes are levied by the District's Board of Directors. The levy is based on assessed valuations determined by the County Assessor generally as of January 1 of each year. The levy is normally set by December 15 by certification to the County Commissioners to put the tax lien on the individual properties as of January 1 of the following year. The County Treasurer collects the determined taxes during the ensuing calendar year. The taxes are payable by April or, if in equal installments, at the taxpayer's election, in February and June. Delinquent taxpayers are notified in August and generally sales of the tax liens on delinquent properties are held in November or December. The County Treasurer remits the taxes collected monthly to the District.

The First Amendment to the Service Plan, approved by the City of Aurora on July 16, 2007, authorized the District to impose an unlimited mill levy on taxable property within its boundaries as a primary source of revenue for repayment of debt service and for operations and maintenance.

The calculation of the taxes levied is displayed on the Property Tax Summary page of the budget using the adopted mill levy imposed by the District.

Specific Ownership Taxes

Specific ownership taxes are set by the State and collected by the County Treasurer, primarily on vehicle licensing within the County as a whole. The specific ownership taxes are allocated by the County Treasurer to all taxing entities within the County. The budget assumes that the District's share will be equal to approximately 7% of the property taxes collected by both the General Fund and the Debt Service Fund. The budget assumes that specific ownership taxes allocable to property taxes collected by the Debt Service Fund will be pledged to debt service on the bonds during the term bonds are outstanding.

Interest Income

Interest earned on the District's available funds has been estimated based on historical interest earnings.

General Operations Fee

The general operations fee is being determined by the amount needed to cover operations and maintenance costs. The District bills its property owners monthly for the general operations fee. The general operations fee is recorded as revenue for budget purposes with no future obligation of repayment.

Expenditures

General and Administrative Expenditures

General and administrative expenditures have been provided based on estimates of the District's Board of Directors and consultants and include the services necessary to maintain the District's administrative viability such as legal, accounting, managerial, insurance, meeting expense, and other administrative expenses.

Expenditures – (continued)

Operations and Maintenance

Operations and maintenance expenditures have been provided based on estimates of the District's Board of Directors and consultants and include costs associated with the operations and maintenance of certain facilities and improvements throughout the District.

Debt Service

The principal and interest payments are provided based on the debt amortization schedules from the General Obligation Refunding Bonds, Series 2017A-1 and Series 2017A-2 (discussed under Debt and Leases).

Debt and Leases

On December 1, 2017, the District refunded its General Obligation Refunding and Improvement Bonds, Series 2007 (the 2007 Bonds) and General Obligation Loan, Series 2016 (the 2016 Loan) by the issuances of \$44,690,000 General Obligation Refunding Bonds, Series 2017A-1, and \$3,945,000 General Obligation Refunding Bonds, Series 2017A-2, respectively (the 2017 Bonds). The proceeds were used for the purposes of (i) refunding the 2007 Bonds and 2016 Loan, (ii) funding the debt service reserve requirement (the 2017A-1 Reserve Fund and the 2017A-2 Reserve Fund); and (iii) paying costs of issuance of the 2017 Bonds.

The 2017 Bonds, mature on December 1, 2047 with an interest rates of 3.000% - 5.000%, are payable semi-annually on June 1 and December 1. The 2017 Bonds maturing on or after December 1, 2047 are subject to redemption prior to maturity, at the option of the District, as whole or in integral multiples of \$5,000, in any order of maturity and in whole or partial maturities, on December 1, 2047 and on any date thereafter, at a redemption price equal to the par amount thereof plus accrued interest to the redemption date.

The 2017 Bonds are general obligations of the District secured by and payable from the Pledged Revenue consisting of moneys derived by the District from the following sources, net of any costs of collection: (i) the Unlimited Mill Levy; (ii) the portion of the Specific Ownership Tax which is collected as a result of the imposition of the Unlimited Mill Levy; and (iii) any other legally available moneys of the District deposited in the Bond Fund or the Reserve Fund.

Approximately 11.5 acres, generally encompassing the Lowe's Home Improvement Warehouse, were excluded from the boundaries of the District on November 7, 2007 (the Excluded Property). Accordingly, the Excluded Property is subject to ad valorem taxes by the District to pay the Series 2017A-1 Bonds but will not be subject to ad valorem taxes to pay the Series 2017A-2 Bonds.

Debt and Leases– (continued)

For the purposes of paying the principal and interest on the Bonds, the Board is to annually determine and certify to the County each year in which the 2017 Bonds remain outstanding, in addition to all other taxes, the Unlimited Mill Levy. The 2017 Bonds are not secured by property lying within the District, but rather by, among other things, the District's obligation to annually determine and certify a rate of levy for ad valorem property taxes in an amount sufficient to pay, along with other legally available revenues, the principal and interest on the 2017 Bonds.

The District has no operating or capital leases.

Reserves

Emergency Reserve

The District has provided for an Emergency Reserve fund equal to at least 3% of fiscal year spending for 2022, as defined under TABOR.

Debt Service Reserve

At time of issuance of the 2017 Bonds, the 2017A-1 Reserve Fund and the 2017A-2 Reserve Fund have been established for the purpose of paying the principal and/or interest on Series 2017A-1 and Series 2017A-2 to the extend the moneys in the Fond Fund are insufficient for such purpose. The 2017A-1

Reserve Fund and 2017A-2 Reserve Fund are required to be maintained at all times in the amounts of \$1,687,625 and \$149,750, respectively.

This information is an integral part of the accompanying budget.

SOUTHLANDS METROPOLITAN DISTRICT NO. 1 SCHEDULE OF OUTSTANDING BONDED DEBT SERVICE REQUIREMENTS TO MATURITY

\$44,690,000 General Obligation Refunding Bonds,

Series 2017 A-1 Dated December 1, 2017

Interest - 3.000% - 5.000%

Payable June 1 and December 1

Principal Due December 1										
<u>Year</u>		Principal		Interest		Total				
	•		•		•					
2022	\$	590,000	\$	2,073,200	\$	2,663,200				
2023		610,000		2,055,500		2,665,500				
2024		685,000		2,034,150		2,719,150				
2025		705,000		2,010,175		2,715,175				
2026		785,000		1,985,500		2,770,500				
2027		815,000		1,958,025		2,773,025				
2028		895,000		1,929,500		2,824,500				
2029		940,000		1,884,750		2,824,750				
2030		1,045,000		1,837,750		2,882,750				
2031		1,100,000		1,785,500		2,885,500				
2032		1,210,000		1,730,500		2,940,500				
2033		1,270,000		1,670,000		2,940,000				
2034		1,390,000		1,606,500		2,996,500				
2035		1,460,000		1,537,000		2,997,000				
2036		1,595,000		1,464,000		3,059,000				
2037		1,675,000		1,384,250		3,059,250				
2038		1,820,000		1,300,500		3,120,500				
2039		1,910,000		1,209,500		3,119,500				
2040		2,070,000		1,114,000		3,184,000				
2041		2,170,000		1,010,500		3,180,500				
2042		2,345,000		902,000		3,247,000				
2043		2,460,000		784,750		3,244,750				
2044		2,650,000		661,750		3,311,750				
2045		2,780,000		529,250		3,309,250				
2046		2,985,000		390,250		3,375,250				
2047		4,820,000		241,000		5,061,000				
	\$	42,780,000	\$	37,089,800	\$	79,869,800				

SOUTHLANDS METROPOLITAN DISTRICT NO. 1 SCHEDULE OF OUTSTANDING BONDED DEBT SERVICE REQUIREMENTS TO MATURITY

\$3,945,000 General Obligation Refunding Bonds, Series 2017 A-2 Dated December 1, 2017 Interest - 3.000% - 5.000% Payable June 1 and December 1 Principal Due December 1

<u>Year</u>	I	Principal	 Interest	Total
		-	 	
2022	\$	50,000	\$ 183,275	\$ 233,275
2023		55,000	181,775	236,775
2024		60,000	179,850	239,850
2025		65,000	177,750	242,750
2026		70,000	175,475	245,475
2027		65,000	173,025	238,025
2028		80,000	170,750	250,750
2029		85,000	166,750	251,750
2030		95,000	162,500	257,500
2031		95,000	157,750	252,750
2032		105,000	153,000	258,000
2033		110,000	147,750	257,750
2034		125,000	142,250	267,250
2035		130,000	136,000	266,000
2036		140,000	129,500	269,500
2037		150,000	122,500	272,500
2038		160,000	115,000	275,000
2039		170,000	107,000	277,000
2040		185,000	98,500	283,500
2041		190,000	89,250	279,250
2042		205,000	79,750	284,750
2043		220,000	69,500	289,500
2044		235,000	58,500	293,500
2045		245,000	46,750	291,750
2046		265,000	34,500	299,500
2047		425,000	 21,250	 446,250
	\$	3,780,000	\$ 3,279,900	\$ 7,059,900

SOUTHLANDS METROPOLITAN DISTRICT NO. 1 SCHEDULE OF OUTSTANDING BONDED DEBT SERVICE REQUIREMENTS TO MATURITY

Year	Principal			Interest	Total		
2022	\$	640,000	\$	2,256,475	\$	2,896,475	
	φ		φ		φ		
2023		665,000		2,237,275		2,902,275	
2024		745,000		2,214,000		2,959,000	
2025		770,000		2,187,925		2,957,925	
2026		855,000		2,160,975		3,015,975	
2027		880,000		2,131,050		3,011,050	
2028		975,000		2,100,250		3,075,250	
2029		1,025,000		2,051,500		3,076,500	
2030		1,140,000		2,000,250		3,140,250	
2031		1,195,000		1,943,250		3,138,250	
2032		1,315,000		1,883,500		3,198,500	
2033		1,380,000		1,817,750		3,197,750	
2034		1,515,000		1,748,750		3,263,750	
2035		1,590,000		1,673,000		3,263,000	
2036		1,735,000		1,593,500		3,328,500	
2037		1,825,000		1,506,750		3,331,750	
2038		1,980,000		1,415,500		3,395,500	
2039		2,080,000		1,316,500		3,396,500	
2040		2,255,000		1,212,500		3,467,500	
2041		2,360,000		1,099,750		3,459,750	
2042		2,550,000		981,750		3,531,750	
2043		2,680,000		854,250		3,534,250	
2044		2,885,000		720,250		3,605,250	
2045		3,025,000		576,000		3,601,000	
2046		3,250,000		424,750		3,674,750	
2047		5,245,000		262,250		5,507,250	
	\$	46,560,000	\$	40,369,700	\$	86,929,700	

SOUTHLANDS METROPOLITAN DISTRICT # 1 Schedule of Cash Position June 30, 2022 Updated as of August 3, 2022

	_	General Fund	01	perations Fee Fund	 Debt Service Fund	Capital Projects Fund	 Total
FirstBank - Checking Account							
Balance as of 06/30/22	\$	22,454.70	\$	610,843.06	\$ -	2,865.00	\$ 636,162.76
Subsequent activities:							
07/01/22 - Directors fees		(322.95)		-	-	-	(322.95)
07/06/22 - Vouchers payable		(13,282.41)		(179,299.49)	-	(2,865.00)	(195,446.90)
07/07/22 - Aurora Water, EFT		-		(9,901.82)	-	-	(9,901.82)
07/07/22 - Xcel, EFT		-		(3,241.04)	-	-	(3,241.04)
07/11/22 - PnP Withdrawal - 07/06		(1.00)		-	-	-	(1.00)
07/15/22 - Voided Bill.com payment		-		1,524.38	-	-	1,524.38
07/15/22 - Vouchers payable July GOF Deposit		-		(1,524.38) 205,125.28	-	-	(1,524.38) 205,125.28
July Debit Card Purchase		-		(5,134.72)	-	-	(5,134.72)
Anticipated Transfer from GF to CPF		- (118,970.93)		(3,134.72)	-	- 118,970.93	(3,134.72)
Anticipated Transfer from GF to CFF Anticipated Transfer from CT		(118,970.93) 150,000.00		-	-	110,970.95	- 150,000.00
Anticipated Vouchers payable		(13,485.87)		- (69,920.04)	-	- (118,970.93)	(202,376.84)
Anticipated Aurora Water, EFT		(15,405.07)		(22,174.77)		(110,570.55)	(22,174.77)
Anticpated Xcel, EFT		-		(3,626.34)	-		(3,626.34)
Annepuleu Acei, El I				522.670.12	 		 549,061.66
	Anticipated Balance	26,391.54		522,070.12	 -	-	 549,001.00
<u>Colotrust</u>							
Balance as of 06/30/22 Subsequent activities:		1,305,614.18		822,877.39	516.67	-	2,129,008.24
07/10/22 - Tax distribution		33,614.99		-	232,483.24	-	266,098.23
07/13/22 - Transfer to A-1 Bond Fund		-		-	(214,848.61)	-	(214,848.61)
07/13/22 - Transfer to A-2 Bond Fund		-		-	(18,151.30)	-	(18,151.30)
07/31/22 - Interest Income		1,879.91		1,201.91	-	-	3,081.82
Anticipated Transfer to 1st Bank		(150,000.00)		-	-	-	(150,000.00)
	Anticipated Balance	1,191,109.08		824,079.30	 -	-	 2,015,188.38
UMB - 2017 A-1 Bond Fund Balance as of 06/30/22 Subsequent activities:		-		-	1,826,338.81	-	1,826,338.81
07/13/22 - Transfer from CT		-		-	214,848.61	-	214,848.61
	Anticipated Balance			-	 2,041,187.42		 2,041,187.42
UMB - 2017 A-1 Reserve Fund	_						
Balance as of 06/30/22 Subsequent activities: None		-		-	1,688,165.53	-	1,688,165.53
	Anticipated Balance			-	 1,688,165.53		 1,688,165.53
<u>UMB - 2017 A-2 Bond Fund</u> Balance as of 06/30/22		-		-	341,853.47	-	341,853.47
Subsequent activities:					511,000117		511,000117
07/13/22 - Transfer from CT		-		-	 18,151.30	-	 18,151.30
	Anticipated Balance	-		-	 360,004.77		 360,004.77
UMB - 2017 A-2 Reserve Fund Balance as of 06/30/22 Subsequent activities: None		-		-	149,797.83	-	149,797.83
	Anticipated Balance	-		-	 149,797.83	-	 149,797.83
	Anticipated Balances <u>\$</u>	1,217,500.62	\$	1,346,749.42	\$ 4,239,155.55	<u>\$</u>	\$ 6,803,405.59

Current Yield - 07/31/22

Colotrust - 1.6547% UMB (Invested in Fidelity money market) - 0.01%

SOUTHLANDS METROPOLITAN DISTRICT #1

Property Tax Reconciliation Schedule

2022

				Prior Year							
		Net Delinquent	Specific				Net	% of Total Prop	erty Total	% of Total P	roperty
	Property	Taxes, Rebates	Ownership		Treasurer's	Due to	Amount	Taxes Receive	d Cash	Taxes Rec	eived
	Taxes	and Abatements	Taxes	Interest	Fees	County	Received	Monthly Y-	Г-D Received	Monthly	Y-T-D
January	\$ -	\$ -	\$ 16,721.37	\$ -	\$ -	\$ -	\$ 16,721.37	0.00% 0	.00% \$ 21,527.98	0.02%	0.02%
February	1,213,296.93	-	19,240.87	-	(18,199.45)	-	1,214,338.35	35.88% 35	.88% 291,082.63	8.51%	8.54%
March	150,134.00	-	19,075.51	(142.91)	(2,249.87)	-	166,816.73	4.44% 40	.32% 1,201,116.53	36.42%	44.95%
April	697,123.49	-	29,593.79	9.69	(10,456.99)	-	716,269.98	20.62% 60	.94% 393,640.78	11.59%	56.54%
May	1,002,278.88	-	15,741.28	-	(15,231.93)	-	1,002,788.23	29.64% 90	.58% 882,800.50	26.75%	83.29%
June	253,580.86	-	16,893.13	(580.76)	(3,795.00)	-	266,098.23	7.50% 98	.08% 519,683.51	15.46%	98.75%
July	-	-	-	-	-	-	-	0.00% 98	.08% 21,871.57	0.05%	98.80%
August	-	-	-	-	-	-	-	0.00% 98	.08% 39,830.50	0.64%	99.44%
September	-	-	-	-	-	-	-	0.00% 98	.08% 22,882.71	0.07%	99.51%
October	-	-	-	-	-	-	-	0.00% 98	.08% 18,758.58	0.02%	99.53%
November	-	-	-	-	-	-	-	0.00% 98	.08% 19,220.97	0.02%	99.55%
December	-	-	-	-	-	-	-	0.00% 98	.08% 19,161.66	0.02%	99.57%
	\$ 3,316,414.16	\$ -	\$ 117,265.95	\$ (713.98)	\$ (49,933.24)	\$ -	\$ 3,383,032.89	98.08% 98	.08% \$ 3,451,577.92	99.57%	99.57%

	Taxes		ŀ	Property Tax	% Collected to
	Levied	% of Levied		Collected	Amt. Levied
Property Tax					
General Fund	\$ 507,927	15.48%	\$	497,893.61	98.02%
Debt Service (2017 A-1)	2,500,561	76.19%		2,451,165.92	98.02%
Debt Service (2017 A-2)	273,499	8.33%		268,096.41	98.02%
Debt Only (2017 A-1)	99,258	100.00%		99,258.22	100.00%
	\$ 3,381,245		\$	3,316,414.16	98.08%
Specific Ownership Tax					
General Fund	\$ 35,555	15.48%	\$	17,674.51	49.70%
Debt Service (2017 A-1)	175,039	76.19%		87,012.98	49.70%
Debt Service (2017 A-2)	19,145	8.33%		9,517.05	49.70%
Debt Only (2017 A-1)	6,948	100.00%		3,061.41	44.10%
-	\$ 236,687		\$	117,265.95	49.54%
Treasurer's Fees					
General Fund	\$ (7,619)	15.48%	\$	(7,497.33)	98.40%
Debt Service (2017 A-1)	(37,508)	76.19%		(36,909.93)	98.40%
Debt Service (2017 A-2)	(4,102)	8.33%		(4,037.03)	98.40%
Debt Only (2017 A-1)	(1,490)	100.00%		(1,488.95)	99.90%
•	\$ (50,719)		\$	(49,933.24)	98.45%

Southlands Metro District #1 2022 General Operations Fees Last Updated: 06/30/22

Last Updated: 06/30/22			<u>г г</u>			r					1	1			
Billing Name	Pe		2022 Budgeted Monthly Billing	January	February	March	April	Мау	June	July	August	September	October	November	December
TJ Max/ Michaels/ Mens Warehouse/ Agree LP	355,168	5.01%	\$ 8,786.27	8,786.27	8,786.27	8,786.27	8,786.27	8,786.27							
T-Moble/ Cleaners/ AKAL Realty	54,060	0.76%		1,337.36	1,337.36	1,337.36	1,337.36	1,337.36							
Centura Health	87,445	1.23%		2,163.25	2,163.25	2,163.25	2,163.25	2,163.25	2,163.25						
Centura Health (Lot 4 - new)	44,612	0.63%		1,103.63	1,103.63	1,103.63	1,103.63	1,103.63	1,103.63						
Centura Health (Lot 5 - new)	39,868	0.56%	\$ 986.27	986.27	986.27	986.27	986.27	986.27	986.27						
Chill's	89,142	1.26%	\$ 2,205.23	2,205.23	2,205.23	2,205.23	2,205.23	2,205.23	2,205.23						
Discount Tire	38,465	0.54%	\$ 951.56	951.56	951.56	951.56	951.56	951.56	951.56	0.06					
Fitzsimons Credit Union	46,533	0.66%	\$ 1,151.15	1,151.15	1,151.15	1,151.15	1,151.15	1,151.15							
GMRI - Olive Garden/Darden	79,836	1.13%		1,975.01	1,975.01	1,975.01	1,975.01	1,975.01	1,975.01	1,975.01	1,975.01	714.96			
GMRI - Red Lobster/Darden	77,186	1.09%		1,909.45	1,909.45	1,909.45	1,909.45	1,909.45	1,799.30						
Good Times	54,758	0.77%	\$ 1,354.62	1,354.62	1,354.62	1,354.62	1,354.62	1,354.62	1,354.62						
HV-1	70,453	0.99%	\$ 1,742.89	1,742.89	1,742.89	1,742.89	1,742.89								
JC Penney	431,671	6.09%	\$ 10,678.83	10,678.83	10,678.83	10,678.83	10,678.83	10,678.83	10,678.83						
Fresh Fund	68,453	0.97%	\$ 1,693.41	1,693.41	1,693.41	1,693.41	1,693.41	1,693.41	835.11						
Lazy Dog	24.096	0.34%	\$ 596.10	596.10	596.10	596.10	596.10	596.10	437.88						
Office Depot/ LEJ Properties	71.045	1.00%		1.757.54	1.757.54	1.757.54	1.757.54	1.757.54	1.757.54						
Jewelers/GNC/ Sprint/ LF-9	43,457	0.61%	\$ 1.075.05	1.075.05	1.075.05	1.075.05	1.075.05	1.075.05							
Mister Hot Shine	68.266	0.96%	\$ 1.688.79	1.688.79	1.688.79	1.688.79	1.688.79	1.688.79	1.688.79						
Mountain Del, LLC/ Colorado Del, LLC	58,738	0.83%	\$ 1,453,08	1.453.08	1.453.08	1,453.08	1,453.08	1.453.08	90.63						
NWSL Power Center, LLC/Southlands PC	1.358.624	19.18%		33.610.11	33.610.11	33.610.11	33.610.11	33,610,11	33.610.11						
NWSLTown Center, LLC./ Southlands TC	1,593,198	22.49%		39,413.09	39,413,09	39,413.09	39.413.09	39,413,09	39.413.09						
On The Border	85,900	1.21%		2.125.02	2.125.02	2.125.02	2,125.02	2,125.02	00,110.00						
Dental/Five Guys/ Pacific Aurora LLC	71.800	1.01%		1.776.21	1.776.21	1,776.21	1,776,21	1.776.21	1.776.21						
PF Changs	76,567	1.08%		1,894,14	1,894,14	1.894.14	1,894,14	1,894,14	31.35						
Marriott/Safari	142.112	2.01%		3.515.62	3.515.62	3.515.62	3.515.62	3.515.62	01.00						
Service Street Auto Repair/Spaco of CO	40,498	0.57%		1.001.85	1.001.85	1.001.85	1.001.85	1.001.85							
/illage Inn	60.205	0.85%		1,489.37	1,489.37	1,489.37	1,489.37	1,489.37							
/ision Works/SLC	47.629	0.67%		1,178.26	1,178,26	1,178.26	1,178.26	1,178.26	1,178.26						
Wal-Mart	1.128.974	15.94%		27.928.96	27.928.96	27.928.96	17.647.60	1,170.20	1,110.20						r
Wal-Mart/Sams Club	566,597	8.00%		14.016.67	14.016.67	14.016.67	14.016.67	735.51							r
Wells Fargo	56,923	0.80%		1.408.18	1,408,18	1,408,18	1.408.18	1.408.18	1.391.31						
Wong 444, Inc./KFC/Harman	51.864	0.73%		1,400.10	1,400.10	1,283.03	1,400.10	1,283.03	67.64						
rong ees, moster os tallitat	51,004	0.1370	÷ 1,205.05	1,205.05	1,205.05	1,205.05	1,205.05	1,203.03	01.04		1	1			
Monthly	7,084,143	100%	\$ 175,250.00	\$ 175,250.00 \$	175,250.00 \$	175,250.00	\$ 164,968.64	132,296.99 \$	105,495.62 \$	1,975.07	\$ 1,975.01	\$ 714.96	\$ -	\$-	\$-
Year-to-Date				\$ 175,250.00 \$	350,500.00 \$	525,750.00	\$ 690,718.64 \$	823,015.63 \$	928,511.25 \$	930,486.32	\$ 932,461.33	\$ 933,176.29	\$ 933,176.29	\$ 933,176.29	\$ 933,176.2

AR - 1		Unearned Rever	ue - 113141	
J Max/ Michaels/ Mens Warehouse/ Agree LP	8,786.27	Discount Tire		0.06
T-Moble/ Cleaners/ AKAL Realty	1,337.36	GMRI - Olive Garden/Darden		4,664.98
Fitzsimons Credit Union	1,151.15			
GMRI - Red Lobster/Darden	110.15		\$	4,665.04
HV-1	3,485.78		-	
Fresh Fund	858.30			
Lazy Dog	158.22			
Jewelers/GNC/ Sprint/ LF-9	1,075.05			
Mountain Del, LLC/ Colorado Del, LLC	1,362.45			
On The Border	2,125.02			
PF Changs	1,862.79			
Marriott/Safari	3,515.62			
Service Street Auto Repair/Spaco of CO	1,001.85			
Village Inn	1,489.37			
Wal-Mart	66,139.28			
Wal-Mart/Sams Club	27,297.83			
Wells Fargo	16.87			
Wong 444, Inc./KFC/Harman	1,215.39			
	\$ 122,988.75	_		
Rounding	-	-		
GOF Revenue	\$ 1,051,500.00			
Penalties				
Office Depot/ LEJ Properties	15.62			
Wal-Mart	6,410.65			
Wal-Mart/Sams Club	3,034.04			
Chili's	94.70			
Mountain Del, LLC/ Colorado Del, LLC	38.16			
HV-1	41.14			
Total	\$ 9,634.31			



June 22, 2022

WORK ORDER #85497

PROPOSAL FOR

NICK MONCADA SPECIAL DISTRICT MANAGEMENT SERVICES SOUTHLANDS METROPOLITAN DISTRICT NO. 1 E. COMMONS AVE. & S. AURORA PARKWAY AURORA, CO 80016

Thank you for allowing us to provide you a quote to perform the work we discussed. We will work out a schedule with you to complete the work once you sign and return this proposal. You may send it via email to service@keesenlandscape.com or fax it to (303) 761-3466. While we do not anticipate any changes to the total cost, Keesen Landscape Management, Inc. does reserve the right to review any proposal that is over 30 days old.

DESCRIPTION OF WORK TO BE PERFORMED

Tree Replacement at Town Square

Remove 3 dead trees in Southlands Town Square and plant

3 new:

2-3" Autumn Blaze Maple

1-2.5" Rain Tree

Sale	\$3,904.99
Sales Tax	\$0.00
Total	\$3,904.99

SOUTHLANDS METROPOLITAN DISTRICT NO. 1 WORK ORDER SUMMARY

INCLUDED SERVICES	SALES TAX	TOTAL COST
Tree Removal and Planting	\$0.00	\$3,904.99
	\$0.00	\$3,904.99

Note: Unless otherwise specified, supplemental watering is not included in this proposal. If additional watering is necessary to protect plant material warranty, a separate proposal will be submitted.

Note: New plant material will be covered by a 1 year/1 replacement warrant. This does not cover any plant material not connected to working irrigation, owner negligence or circumstances beyond our control including freeze and rodent damage. This includes trees, shrubs and perennial plant material only.

Force Majeure and Delays

Landscape Contractor's installation and warranty obligations under this work order are accepted subject to strikes, labor troubles (including strikes or labor troubles affecting any suppliers of Landscape Contractor), floods, fires, acts of God, accidents, delays, shortages of equipment, contingencies of transportation, and other causes of like or different character beyond the control of the Landscape Contractor. Impossibility of performance by reason of any legislative, executive, or judicial act of any government authority shall excuse performance of or delay in performance of this work order.

Patrick Atkinson

Date 6/22/2022

Keesen Landscape Management, Inc.

Date

By

SPECIAL DISTRICT MANAGEMENT SERVICES

as Agent for

SOUTHLANDS METROPOLITAN DISTRICT NO. 1

Note: Unless otherwise specified in the work order, all required irrigation repairs/modifications will be done at a time and materials rate of \$68.00 per man hour.



August 12, 2022

WORK ORDER #88027

PROPOSAL FOR

MARTIN LILES M&J WILKOW SOUTHLANDS TOWN CENTER 6305 S MAIN ST AURORA, CO 80016

Thank you for allowing us to provide you a quote to perform the work we discussed. We will work out a schedule with you to complete the work once you sign and return this proposal. You may send it via email to service@keesenlandscape.com or fax it to (303) 761-3466. While we do not anticipate any changes to the total cost, Keesen Landscape Management, Inc. does reserve the right to review any proposal that is over 30 days old.

DESCRIPTION OF WORK TO BE PERFORMED

Main Street plant Replacements

Main Street plant replacements:

West side Plants

East Side Plants

Let me know if you want a list of plants by the side.

Sale	\$8,764.93
Sales Tax	\$511.80
Total	\$9,276.73

SOUTHLANDS TOWN CENTER WORK ORDER SUMMARY

	SALES TAX	TOTAL COST
West Side Plant Replacements	\$246.51	\$4,499.38

Contract No 88027	Southlands Town Center		August 12, 2022
East Side Plants Replacements		\$265.29	\$4,777.35
		\$511.80	\$9,276.73

Note: Unless otherwise specified, supplemental watering is not included in this proposal. If additional watering is necessary to protect plant material warranty, a separate proposal will be submitted.

Note: New plant material will be covered by a 1 year/1 replacement warrant. This does not cover any plant material not connected to working irrigation, owner negligence or circumstances beyond our control including freeze and rodent damage. This includes trees, shrubs and perennial plant material only.

Force Majeure and Delays

Landscape Contractor's installation and warranty obligations under this work order are accepted subject to strikes, labor troubles (including strikes or labor troubles affecting any suppliers of Landscape Contractor), floods, fires, acts of God, accidents, delays, shortages of equipment, contingencies of transportation, and other causes of like or different character beyond the control of the Landscape Contractor. Impossibility of performance by reason of any legislative, executive, or judicial act of any government authority shall excuse performance of or delay in performance of this work order.

Ву			

Patrick Atkinson

Date 8/12/2022

Keesen Landscape Management, Inc.

Ву

Date

M&J WILKOW

as Agent for

SOUTHLANDS TOWN CENTER

Note: Unless otherwise specified in the work order, all required irrigation repairs/modifications will be done at a time and materials rate of \$68.00 per man hour.



1801 W. 64th Ln Denver, CO. 80221 8/2/2022 - Revised

Attn: Martin Liles Project: Southlands Mall

Scope of Work: Identify, and replace dead bushes and shrubbery along Main Street at Southlands Mall. Job to be performed is removing and trashing dead shrubs and replanting with the shrub of the same species.

Pricing Proposal:

Currant Alpine: 9 shrubs	\$29.75/ea
Private Lodense: 24 shrubs	\$31.75/ea
Maynight Salvia: 25 shrubs	\$13/75/ea
Bailey Dog Wood: 12 shrubs	\$29.75/ea
Labor Hours: 16 man hours	\$45/hr

Total Cost: \$2617.75

ACCEPTED: Longhill Contracting is authorized to proceed with this work at the price quoted above.

Auth	orized	l Sign	ature:

Full Spectrum Lighting, Inc.

1630 W 54th Pl. 303-204-0949


Estimate

Date	Estimate #
8/10/2022	1412

Name / Address

Southlands Metro Dist. #1 141 Union Boulevard Suite 150 Lakewood, Co. 80228-1898 Special District Mgt. Services

			Project
Description	Qty	Cost	Total
Electrical Retrofit 169 pole lights to LED. Keep circuit at 480V, replacing with new transformer to retrofit fixture to 277V LED bulb. Materials -HID-27E26-840-BYP-PT-RAB -KTAT-70-480-277 -E27 2 Hole Mount 6" Leads-LH0422 -Aluminum mounting bracket Note: This does not include new tear drop globes. If we need to replace wiring there will be additional cost at time and material.	253 169	80.00	20,240.00 42,250.00
		Total	\$62,490.00



This information has been obtained from sources believed to be reliable. We have not verified it and make no guarantee, warranty or representation about it. Any projections, opinions, assumptions or estimates used are for example only and do not represent the current or future performance of the property. You and your advisors should conduct a careful, independent investigation of the property to determine to your satisfaction the suitability of the property for your needs.



ROCKY MOUNTAIN PARKING LOT SERVICES, INC.

10890 E. 47th Ave. Denver CO 80239

www.parkinglotservices.com

Office: (303) 576-9050 Fax: (303) 576-9051 Toll Free: (888) 827-9820

mail@parkinglotservices.com

STRIPING BID

Company Name & Contact	[:] M&J Wilkow / Augustina Edwards		BID# 22-48
E-Mail Address	aedwards@wilkow.com	Phone: 720-544-1787	
Job Name & Addres	s Southlands – Metro I	Dist / 6155 Main St	
Billing Address			
PO (if required)	:		
 Striping completed by Traffic spec paint will 		with glass bead application available.	
 Stencils are lined, center 			
 Paint will not adhere per 			
	med during time of least traffic :	interference.	
		rking lot. Notices to tenants and a tow truc	k are
7. Sprinkler systems need	s to be turned off one day befor	e and day of striping.	
8. All services are weather			
		e and \$2,000,000.00 Liability insurance	
available upon request.			
10. We accept Visa and M			
11. Prevailing Wages are n	ot included, an additional 25%	will be added to final cost if needed.	
Restripe All Lines	R	epaint X -Walk Bars	
30 – White Handicaps	2	- 20" ONE WAY stencils	
5-8' ONLY stencils	2	4 – Bike Stencils	
24 – 12" LANE stencils	1	54 – Arrows	

TOTAL- \$13,900.00

**** There will be a trip charge of \$200.00 for returns due to vehicles in lot or obstructions to job completion on scheduled date. Ground to air temperature should be 50/50 for best results and lasting adherence. We cannot guarantee paint adherence between October 15st and April 15st. **** Terms: Net 30 - 2% Service Charge on past due amounts.

ESTIMATED BY:	Pat Taylor	DATE:	4-25-22

ACCEPTED BY:	DATE:	
ACCEFIED DI:	DATE:	



12365 Dumont Way Littleton, CO 80125 (p) 303.791.8300 (f) 303.791.6616

То:	Metro District	Contact:	Skye Bailey
Address:	6155 S Main St Suite 260	Phone:	(303) 627-5001
	Aurora, CO 80016	Fax:	
Project Name:	Metro Striping	Bid Number:	CO004614
Project Location:	6155 S Main St, Aurora, CO	Bid Date:	8/4/2022

Item Description

Pavement Markings

Double Center Line- 5,676 LF Per Ft. 4- 18,061 LF Stop Bar- 78 New 2x5-8 Cross Walk- 91 90- Arrow- 125 8 Foot Letter [only]- 5 18 Ft Stalls- 289 Handicap-Blue Background- 30 Hashmark Small- 10 Hashmark Large- 5 Bike Guy- 23 42'-Arrow- 23 Triangle Bike Lane - 23 12' Stencil- 23

*Estimate Is For Work To Performed Over 5 Phases. Additional MOB's Required Due To Vehicles Or Equipment Parked In Scheduled Work Area Subject To Additional MOB Fee (per MOB)

Total Bid Price: \$23,426.67

Notes:

• IMPORTANT NOTICE:

Estimated material costs are included in total price. In order to hold pricing, this proposal must be signed and returned within 15 days from the bid date specified above. Due to the pricing volatility of our industry at the moment, Sunland reserves the right to update pricing at any time prior to start of work.

Additional (downtime/mobilization) charges may result from delays beyond the control of Sunland Asphalt (or its subcontractors) which prohibit the above mentioned work from being completed as scheduled. (i.e., unmoved vehicles, disregard for Sunland traffic control, sanitation/delivery services, sprinkler runoff, etc.)

-This bid excludes Subgrade prep.

- Sunland Asphalt will not be held liable for any underground cables, electrical lines, water lines, irrigation lines, sensor loops or any other underground obstruction not buried to a depth less than 18" below the existing finished grade

-There will be an extra charge based on time and material for the removal and replacement of dirt or soil if soft or frozen is found unless otherwise noted.

-Additional cost will apply if winter protection for concrete is required. Proposal excludes any landscaping repair, backfill or repair to un-marked irrigation lines and sprinkler heads.

- No permits, fees, bonds, prevailing wages, compaction tests, staking, layout, ADA compliance, new parking blocks, testing, utility adjustments, concrete, water/meter, weed kill, signs of any kind or offsite barricades in price unless noted in contract.

- Sunland Asphalt warrantees all labor and materials for a period of 12 months upon completion of project.

- Sunland Asphalt is not responsible for defects in the finished pavement resulting from deficiencies in grade or base. Such deficiencies may include, but are not limited to, cracking, segregation, low areas, high areas or settling.

- Any pre-existing ADA compliance issues are excluded from the contract unless specifically stated in the proposal. Proposal excludes any concrete or asphalt testing. Sunland Asphalt can not guarantee drainage less than 2%.

Total Price

\$23,426.67

• Sunland Asphalt Terms and Conditions:

Contractor hereby accepts the terms of the attached Contract subject to the provisions as defined on the Contract Agreement as well as the Owner's Agreement with the terms set forth in this Addendum. This Addendum is attached hereto and incorporated herein by reference. If any of the terms of the Contract are inconsistent with the terms of this Addendum, then this Addendum shall be controlling and the parties shall be bound by the terms and conditions of this Addendum.

ACCEPTED: The above prices, specifications and conditions are satisfactory and are hereby accepted.	CONFIRMED: Sunland Asphalt	& Construction Inc.
Buyer:		
Signature:	Authorized Signature	:
Date of Acceptance:	Project Consultant:	Eric Andre
		720-614-1444 eandre@sunlandasphalt.com

Sunland Asphalt Terms and Conditions:

Contractor hereby accepts the terms of the attached Contract subject to the provisions as defined on the Contract Agreement as well as the Owner's Agreement with the terms set forth in this Addendum. This Addendum is attached hereto and incorporated herein by reference. If any of the terms of the Contract are inconsistent with the terms of this Addendum, then this Addendum shall be controlling and the parties shall be bound by the terms and conditions of this Addendum.

1. PAYMENT

Contractor shall be paid a monthly progress payment within 15 days after receipt of the payment by the Owner for the value of work performed. Final payment, including all retention, shall be due 15 days after the work described in the Proposal is substantially completed. No provision of this agreement shall serve to void the Contractor's entitlement to payment for properly performed work.

• 2. INTEREST AND EXPENSES

All sums not paid when due shall bear an interest rate of 1 1/2% per month or the maximum legal rate permitted by law, whichever is less, and all costs of collection, including a reasonable attorneys' fee, shall be paid by Owner.

• 3. ATTORNEYS' FEES

In the event of litigation or collection efforts by Contractor, the prevailing party shall be reimbursed for its reasonable attorneys' fees, which shall include all costs that would normally be passed through to the client, specifically but not limited to research charges, travel costs, expert witness costs, copying costs, mailing costs, facsimile costs, had-delivery costs, Federal Express or Express Mail costs, taxable costs and disbursements. • 4. CONTINUED PERFORMANCE

Nothing in this subcontract agreement shall require the Contractor to continue performance if timely payments are not made to Contractor for suitably performed work.

• 5. BACK CHARGES

No back charges or claim of the Owner for services shall be valid except by an agreement in writing by the Contractor before the work is executed, except in the case of the Contractors failure to meet any requirement of the subcontract agreement. In such event, the Owner shall notify the Contractor of such default, in writing, and allow the Contractor reasonable time to correct any deficiency before incurring any cost chargeable to the Contractor.

6. WORK AREAS

Owner is to prepare all work areas so as to be acceptable for Contractor work under the contract. Contractor will not be called upon to start work until sufficient areas are ready to insure continued work.

• 7. TIME FOR PERFORMANCE

Contractor shall be given a reasonable time in which to commence and complete the performance of the contract. Contractor shall not be responsible for delays or default where occasioned by any causes of any kind and extent beyond its control, including but not limited to: delay caused by Owner, architect and/or engineers, delays in transportation, shortages of raw materials, civil disorders, labor difficulties, vendor allocations, fires, floods, accident hazardous waste or controlled substances and acts of God. Contractor shall be entitled to equitable adjustment in the subcontract amount for additional costs due to unanticipated project delays or accelerations. Contractor shall not be obligated to provide any labor or materials outside the scope of work unless Owner shall first agree in writing to equitably adjust the subcontract amount to be paid Contractor.

• 8. WORKMANSHIP

All workmanship is guaranteed against defects for a period of one year from the date of substantial completion of installation. This warranty is in lieu of all other warranties, express or implied, including any warranties of merchantability or fitness for a particular purpose. The exclusive remedy shall be that Contractor will replace or repair any part of its work which is found to be defective. Contractor shall not be responsible for special, incidental or consequential damages. Contractor shall not be responsible for damage to its work by other parties or for improper use of equipment by other Standard of industry practice and will override strict compliance and strict performance.

• 9. WORK HOURS

Work called for herein is to be performed during Contractor's regular working hours as agreed to by the Owner and the Contractor.

10. NOTICE

Any notice or written claim required by the contract documents to be submitted to the Owner, on account of charges, extras, delays, acceleration, or otherwise, shall be furnished within a time period, and in a manner to permit the Owner to satisfy the requirements of the contract documents, notwithstanding any shorter time period otherwise provided.

• 11. LIEN RIGHTS

Nothing in this agreement shall serve to void Contractor's right to file a lien or claim on its behalf in the event that any payment to Contractor is not timely made.

• 12. LABOR

Contractor shall not be bound by any of Owner's labor agreements (in whole or in part).

• 13. LIQUIDATED DAMAGES

The Owner shall make no demand for liquidated damages for delays in any sum in excess of such amounts as may be specifically named in this Addendum and no liquidated damages may be assessed against Contractor for more than the amount paid by the Owner for unexcused delays to the event actually caused by the Contractor.

• 14. SCHEDULE

Contractor shall submit a schedule to Owner, Owner will review and notify Contractor of any schedule conflict. If Contractor finds it necessary to change his schedule, owner will give his best effort to meet this change in schedule. Contractor shall not be penalized for non-performance and will be paid for work performed.

• 15. INSURANCE RESTRICTION

Notwithstanding any provision to the contrary, Contractor shall maintain the types and limitations on insurance as shown on the attached certificate of insurance. Contractor is not required to waive any claims or rights of subrogation against the Owner or any others for losses and claims covered or paid by Owner's workers compensation or general liability insurance. Acceptance of the Certificate of Insurance constitutes acceptance of the insurance of Contractor, including any additional insured requirements. In addition, Contractor shall not provide completed operations under an additional insured requirement.

• 16. INDEMNITY, HOLD HARMLESS RESTRICTION

Any indemnification or hold harmless obligation of the Contractor shall extend only to claims relating to bodily injury and property damage and then only to that part or proportion of any claim damage, loss or defect that results from the negligence or intentional act of the indemnitor or someone for whom it is responsible. Contractor shall not under any circumstance have a duty to defend. Nothing in this agreement shall require the Contractor to indemnify any other party from any damages including expenses and attorneys' fees to persons or property for any amount exceeding the degree Contractor directly caused such damages. Contractor shall not be responsible for fines or assessments made against Owner and Contractor. Contractor retains all rights of subrogation. Contractor will not indemnify anybody for any actions except for Contractor's own negligence and only in the proportional amount of their negligence.

• 17. RIGHT TO RELY

Contractor shall rely on plans, drawings, specifications and other information provided by Owner, Owner, Architect or representatives of each. Contractor assumes no risk for unknown or unforeseen conditions not evident from the plans, drawings, specifications or other information provided to Contractor.

• 18. HAZARDOUS WASTE

Contractor shall have no obligation to handle (that is, to remove, treat or transport) any substance which is considered hazardous waste or substance under state or federal law ("hazardous waste"). Handling hazardous waste shall be outside the scope of work of this agreement. Title to all hazardous waste shall remain with others and shall not be property of Contractor.

19. DISPUTE RESOLUTION

Final determination of contract compliance and all dispute resolutions shall be handled in the jurisdiction and venue of Maricopa County, Arizona, and be governed by the laws of Arizona.

From: Martin Liles <<u>mliles@wilkow.com</u>> Sent: Friday, July 29, 2022 11:16 AM To: Ann Finn <<u>afinn@sdmsi.com</u>> Subject: Security Budget

Ann –

I've been analyzing our security expenses for Southlands over the past few months. Security is our largest line item expense to the property and continues to increase do to demanding wages in the market. Attached is the projected costs for security that are allocated to Southlands TC LLC. I would like to present to the Metro District the below expenses be shared as the listed items benefit both the Metro District and Southlands TC LLC.

The additional fees for the Metro District would consist of a 50/50 split on the following items:

Non-Labor Items monthly Costs at 50% consist of the following;

- Office Rent: \$2,779.17
- HeliAUS Devices: \$225
- Healthcare: \$175
- Patrol Vehicle: \$650

\$3,829/month

As you aware, Allied is stationed on property and rents one of our spaces. Southlands TC LLC pays for all utilities, office materials and incidentals for the premises and will continue to do so.

I've also attached the Southlands TC LLC projected cost sheet for review.

I would like to present the modifications in our next board meeting and for the shared fees to be implemented August 1st.

Thanks

Martin Liles

Regional Vice President & General Manager of Southlands

M&JWILKOW

6155 S Main Street Suite 260 Aurora, CO 80016 Tel: 303-627-5405 Cell: 303-720-1844 <u>MLiles@wilkow.com</u> www.wilkow.com

This e-mail and all attachments may contain privileged and confidential information intended solely for the use of the addressee(s). If the reader of this message is not the intended recipient, you are hereby notified that any reading, dissemination, distribution, copying, or other use of this e-mail or its attachments is strictly prohibited. If you have received this message in error, please notify the sender immediately by telephone or by electronic mail, and delete this message and all copies and backups thereof. This e-mail is not intended to create, nor shall it be construed to create, any legally binding obligation on behalf of the sender, M & J Wilkow, Ltd. or any affiliate thereof.



Annual Cost Projection Worksheet

CLIENT COMPANY:	M&J Wilkow
PROPERTY NAME:	Southlands
DATE PREPARED:	7/26/2022

EFFECTIVE DATE:

1/1/2023

SECTION 1: CONTRACT HOURS	WEEKLY	[OT/HOLIDAY	OT/HOLIDAY			
POSITION	HOURS	WAGE RATE	BILL RATE	WAGE RATE	BILL RATE	WEEKLY BILLING	ANNUAL BILLING	
Account Manager	40	\$ 35.75	\$ 50.05	\$ 53.63	\$ 75.08	\$ 2,002.00	\$ 104,104.00	
Shift Supervisor	80	\$ 21.00	\$ 29.40	\$ 31.50	\$ 44.10	\$ 2,352.00	\$ 122,304.00	
Security Professional (Graveyard)	40	\$ 21.00	\$ 29.40	\$ 31.50	\$ 44.10	\$ 1,176.00	\$ 61,152.00	
Security Professional	186	\$ 20.00	\$ 28.00	\$ 30.00	\$ 42.00	\$ 5,208.00	\$ 270,816.00	
	0	\$-	\$-	\$-	\$-	\$-	\$-	
	0	\$-	\$-	\$-	\$-	\$-	\$-	
	0	\$-	\$-	\$-	\$-	\$-	\$-	
	0	\$ -	\$-	\$-	\$-	\$ -	\$ -	
TOTALS:	346					\$ 10,738.00	\$ 558,376.00	
SECTION 2: TECHNOLOGY		Γ						
ITEMS		QUANTITY	UNIT COST	MONTHLY BILLING	BILLING	ANNUAL NOTES BILLING		
INCIDENT REPORTING/MANAGEME		1	\$-	\$-	\$-		JDED (CyCop)	
LEARNING MANAGEMENT SYSTEM FO		1	\$ -	\$ -	\$ -	•	nline Web-Based LMS)	
WORKFORCE MANAGEMENT S		1	\$ -	\$ -	\$ -		ed (WinTeam)	
LAPTOP/DESKTOP COMPUT		1	\$ -	\$-	\$-	INCLUI	DED (1 Laptop)	
		0	\$ - \$ -	\$ -	\$ -		N/A	
TABLET WITH WIRELESS CONNE SMART PHONE WITH HELIA		0	Ŷ	\$ - \$ 450.00	\$ - \$ 5,400.00	Dille	N/A	
SMART PHONE WITH HELIA SMART PHONE	.03	1	\$ 150.00 \$ 95.00	\$ 450.00 \$ 95.00	\$ 5,400.00 \$ 1,140.00		d as Incurred d as Incurred	
SWARTHONE	TOTALS:	8	Ş 93.00	\$ 545.00	\$ 1,140.00 \$ 6,540.00	Dillet		
SECTION 3: HEALTHCARE	TOTALS.	8		Ş 343.00	Ş 0,540.00	l		
HEALTHCARE COVERAGE		PROJECTED #	PREMIUM PER	MONTHLY	ANNUAL	NOTES		
Hourby Stoff		OF ENROLLEES	ENROLLEE \$ 175.00	SILLING	BILLING \$-	Billo	d as Insurrod	
Hourly Staff Salaried Management Staff		1	\$ 175.00 \$ 450.00	\$ - \$ 450.00	\$ - \$ 5,400.00		d as Incurred d as Incurred	
Salahed Management Sta	TOTALS:	0	÷ +50.00	\$ 450.00	\$ 5,400.00		n anticipated participation	
SECTION 4: ADDITIONAL BENEFITS	TOTALS.	, v		Ş 450.00	\$ 5,400.00	Estimates based o		
BENEFIT MONTH			MONTHLY BILLING	ANNUAL BILLING		NOTES		
VACATION/ANNIVERSARY BONUS								
VACATION/ANNIVE	SARY BONUS				1 w	veek after one vear based	t on hours worked	
-			\$ -	\$ -		veek after one year based Presidents Day, MLK Day, Memori		
VACATION/ANNIVEF HOLIDAY PREM			\$ - \$ -	\$ - \$ -			al Day, Independence Day, Labor Day,	
-	IUM PAY		\$ - \$ - \$ -	\$ - \$ - \$ -	New Year's Day, F	Presidents Day, MLK Day, Memori	al Day, Independence Day, Labor Day, ristmas Day	
HOLIDAY PREM SICK PA	IUM PAY	TOTALS:	\$ - \$ - \$ -	\$ - \$ -	New Year's Day, F	Presidents Day, MLK Day, Memori Thanksgiving Day and Ch	al Day, Independence Day, Labor Day, ristmas Day	
HOLIDAY PREM	IUM PAY	TOTALS: QUANTITY	\$ - \$ - \$ -	\$ - \$ - \$ - \$ - \$ - \$ -	New Year's Day, P	Presidents Day, MLK Day, Memori Thanksgiving Day and Ch	al Day, Independence Day, Labor Day, ristmas Day	
HOLIDAY PREM SICK PA SECTION 5: VEHICLES VEHICLE TYPE	IUM PAY	QUANTITY	\$ - \$ - \$ - \$ - UNIT COST	\$ - \$ - \$ - \$ - \$ - \$ - BILLING	New Year's Day, P ANNUAL BILLING	Presidents Day, MLK Day, Memori Thanksgiving Day and Ch Billed as incurred where	al Day, Independence Day, Labor Day, ristmas Day required by law NOTES	
HOLIDAY PREM SICK PA SECTION 5: VEHICLES VEHICLE TYPE PATROL VEHICLE	IUM PAY	QUANTITY 1	\$ - \$ - \$ - \$ - \$ - \$ \$ - \$ \$ - \$ \$ - \$	\$ - \$ - \$ - \$ - \$ - \$ - \$ \$ - \$ \$ \$ \$ \$	New Year's Day, R ANNUAL BILLING \$ 15,600.00	Presidents Day, MLK Day, Memori Thanksgiving Day and Ch Billed as incurred where	al Day, Independence Day, Labor Day, ristmas Day required by law NOTES led As Incurred	
HOLIDAY PREM SICK PA SECTION 5: VEHICLES VEHICLE TYPE PATROL VEHICLE GOLF CART	IUM PAY	QUANTITY 1 0	\$ - \$ - \$ - \$ - \$ - \$ \$ - \$	\$ - \$ - \$ - \$ - \$ - \$ - \$ \$ - \$ \$ \$ \$ \$	New Year's Day, R ANNUAL BILLING \$ 15,600.00 \$ -	Presidents Day, MLK Day, Memori Thanksgiving Day and Ch Billed as incurred where	al Day, Independence Day, Labor Day, ristmas Day required by law NOTES led As Incurred N/A	
HOLIDAY PREM SICK PA SECTION 5: VEHICLES VEHICLE TYPE PATROL VEHICLE	IUM PAY Y	QUANTITY 1 0 0	\$ - \$ - \$ - \$ - \$ - \$ \$ - \$ \$ 1,300.00 \$ - \$ -	\$ - \$ - \$ - \$ - \$ - \$ - \$ \$ - \$ \$ 1,300.00 \$ - \$ - \$ -	New Year's Day, P ANNUAL BILLING \$ 15,600.00 \$ - \$ -	Presidents Day, MLK Day, Memori Thanksgiving Day and Ch Billed as incurred where	al Day, Independence Day, Labor Day, ristmas Day required by law NOTES led As Incurred	
HOLIDAY PREM SICK PA SECTION 5: VEHICLES VEHICLE TYPE PATROL VEHICLE GOLF CART BICYCLE	IUM PAY	QUANTITY 1 0	\$ - \$ - \$ - \$ - \$ - \$ \$ - \$	\$ - \$ - \$ - \$ - \$ - \$ - \$ \$ - \$ \$ 1,300.00 \$ - \$ - \$ -	New Year's Day, F	Presidents Day, MLK Day, Memori Thanksgiving Day and Ch Billed as incurred where	al Day, Independence Day, Labor Day, ristmas Day required by law NOTES led As Incurred N/A	
HOLIDAY PREM SICK PA SECTION 5: VEHICLES VEHICLE TYPE PATROL VEHICLE GOLF CART BICYCLE SECTION 6: TRAINING	IUM PAY Y	QUANTITY 1 0 0	\$ - \$ - \$ - \$ - \$ - \$ \$ - \$ \$ 1,300.00 \$ - \$ -	\$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ -	New Year's Day, P ANNUAL BILLING \$ 15,600.00 \$ - \$ - \$ 15,600.00 ANNUAL	Presidents Day, MLK Day, Memori Thanksgiving Day and Ch Billed as incurred where	al Day, Independence Day, Labor Day, ristmas Day required by law NOTES led As Incurred N/A	
HOLIDAY PREM SICK PA SECTION 5: VEHICLES VEHICLE TYPE PATROL VEHICLE GOLF CART BICYCLE SECTION 6: TRAINING TR	IUM PAY Y TOTALS:	QUANTITY 1 0 0 1	\$ - \$ - \$ - \$ - \$ - \$ \$ - \$ \$ 1,300.00 \$ - \$ -	\$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ -	New Year's Day, P ANNUAL BILLING \$ 15,600.00 \$ - \$ 2 \$ 15,600.00 ANNUAL BILLING	Presidents Day, MLK Day, Memori Thanksgiving Day and Ch Billed as incurred where Fuel Bil	al Day, Independence Day, Labor Day, ristmas Day required by law NOTES led As Incurred N/A N/A N/A	
HOLIDAY PREM SICK PA SECTION 5: VEHICLES VEHICLE TYPE PATROL VEHICLE GOLF CART BICYCLE SECTION 6: TRAINING TR PRE-ASSIGN	IUM PAY Y TOTALS: AINING TYPE MENT/BASIC TR/	QUANTITY 1 0 0 1 NINING	\$ - \$ - \$ - \$ - \$ - \$ \$ - \$ \$ 1,300.00 \$ - \$ -	\$ - \$ - \$ - \$ - \$ MONTHLY BILLING \$ 1,300.00 \$ - \$ 1,300.00 \$	New Year's Day, P ANNUAL BILLING \$ 15,600.00 \$ - \$ 2 \$ 15,600.00 ANNUAL BILLING \$ -	Presidents Day, MLK Day, Memori Thanksgiving Day and Ch Billed as incurred where Fuel Bil	al Day, Independence Day, Labor Day, ristmas Day required by law NOTES led As Incurred N/A N/A N/A NOTES NOTES	
HOLIDAY PREM SICK PA SECTION 5: VEHICLES VEHICLE TYPE PATROL VEHICLE GOLF CART BICYCLE SECTION 6: TRAINING TR PRE-ASSIGNI CPR, FIRST	IUM PAY Y TOTALS: AINING TYPE MENT/BASIC TR/ AID, & AED TRAI	QUANTITY 1 0 0 1 1 AINING NING	\$ - \$ - \$ - \$ - \$ - \$ \$ - \$ \$ 1,300.00 \$ - \$ -	\$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ -	New Year's Day, P ANNUAL BILLING \$ 15,600.00 \$ - \$ - \$ 15,600.00 ANNUAL BILLING \$ - \$ - \$ - \$ 15,600.00	Presidents Day, MLK Day, Memori Thanksgiving Day and Ch Billed as incurred where Fuel Bil Fuel Bil	al Day, Independence Day, Labor Day, ristmas Day required by law NOTES led As Incurred N/A N/A N/A NOTES NOTES NOTES	
HOLIDAY PREM SICK PA SECTION 5: VEHICLES VEHICLE TYPE PATROL VEHICLE GOLF CART BICYCLE SECTION 6: TRAINING TR PRE-ASSIGNI CPR, FIRST	IUM PAY Y TOTALS: AINING TYPE MENT/BASIC TR/	QUANTITY 1 0 0 1 1 AINING NING	\$ - \$ - \$ - \$ - \$ - \$ \$ - \$ \$ 1,300.00 \$ - \$ -	\$	New Year's Day, P ANNUAL BILLING \$ 15,600.00 \$ - \$ 2 \$ 15,600.00 ANNUAL BILLING \$ -	Presidents Day, MLK Day, Memori Thanksgiving Day and Ch Billed as incurred where Fuel Bil Fuel Bil	al Day, Independence Day, Labor Day, ristmas Day required by law NOTES led As Incurred N/A N/A N/A NOTES NOTES	
HOLIDAY PREM SICK PA SECTION 5: VEHICLES VEHICLE TYPE PATROL VEHICLE GOLF CART BICYCLE SECTION 6: TRAINING TR PRE-ASSIGNI CPR, FIRST	IUM PAY Y TOTALS: AINING TYPE MENT/BASIC TR/ AID, & AED TRAI G/OTHER EDUC/	QUANTITY 1 0 0 1 1 AINING NING	\$ - \$ - \$ UNIT COST UNIT COST \$ 1,300.00 \$ - \$ 1,300.00	\$	New Year's Day, P ANNUAL BILLING \$ 15,600.00 \$ - \$ - \$ 15,600.00 \$ ANNUAL BILLING \$ - \$ - \$. \$. \$. \$. \$. \$. \$. \$.	Presidents Day, MLK Day, Memori Thanksgiving Day and Ch Billed as incurred where Fuel Bil Fuel Bil	al Day, Independence Day, Labor Day, ristmas Day required by law NOTES led As Incurred N/A N/A N/A NOTES NOTES NOTES	
HOLIDAY PREM SICK PA SECTION 5: VEHICLES VEHICLE TYPE PATROL VEHICLE GOLF CART BICYCLE SECTION 6: TRAINING TR PRE-ASSIGNI CPR, FIRST CONTINUIN	IUM PAY Y TOTALS: AINING TYPE MENT/BASIC TR/ AID, & AED TRAI G/OTHER EDUC/	QUANTITY 1 0 0 1 1 AINING NING	\$ - \$ - \$ UNIT COST UNIT COST \$ 1,300.00 \$ - \$ 1,300.00	 \$ - \$ - \$ - \$ - \$ 1,300.00 \$ - \$ 1,300.00 \$ - \$ 1,300.00 \$ - > - > - > - -	New Year's Day, R ANNUAL BILLING \$ 15,600.00 \$ \$ \$ 15,600.00 \$	Presidents Day, MLK Day, Memori Thanksgiving Day and Ch Billed as incurred where Fuel Bil Fuel Bil	al Day, Independence Day, Labor Day, ristmas Day required by law NOTES led As Incurred N/A N/A N/A NOTES NOTES NOTES	
HOLIDAY PREM SICK PA SECTION 5: VEHICLES VEHICLE TYPE PATROL VEHICLE GOLF CART BICYCLE SECTION 6: TRAINING TR PRE-ASSIGNI CPR, FIRST CONTINUIN	IUM PAY Y TOTALS: AINING TYPE MENT/BASIC TR/ AID, & AED TRAI G/OTHER EDUC/	QUANTITY 1 0 0 1 1 AINING NING	\$ - \$ - \$ UNIT COST UNIT COST \$ 1,300.00 \$ - \$ 1,300.00	 \$ - \$ - \$ - \$ - \$ 1,300.00 \$ - \$ 1,300.00 \$ - \$ 1,300.00 \$ - -	New Year's Day, R ANNUAL BILLING \$ 15,600.00 \$ \$ \$ 15,600.00 \$	Presidents Day, MLK Day, Memori Thanksgiving Day and Ch Billed as incurred where Fuel Bil WITHIN 90 D/	al Day, Independence Day, Labor Day, ristmas Day required by law NOTES led As Incurred N/A N/A N/A N/A NOTES NCLUDED AYS OF EMPLOYMENT NCLUDED NOTES NOTES	
HOLIDAY PREM SICK PA SECTION 5: VEHICLES VEHICLE TYPE PATROL VEHICLE GOLF CART BICYCLE SECTION 6: TRAINING TR PRE-ASSIGNI CPR, FIRST CONTINUIN SECTION 7: UNIFORMS, EQUIPMENT	IUM PAY Y TOTALS: AINING TYPE MENT/BASIC TR/ AID, & AED TRAI G/OTHER EDUC/ AND OTHER ITEM	QUANTITY 1 0 1 AINING NING ATION	\$ - \$ - \$ UNIT COST UNIT COST \$ 1,300.00 \$ - \$ 1,300.00	\$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ 1,300.00 \$ - \$ 1,300.00 \$ - \$ 1,300.00 \$ - \$ 1,300.00 \$ - <td< td=""><td>New Year's Day, R New Year's Day, R Null BILLING 15,600.00 16,600.00 16,600.00 17,000 18,000 19,000 19,000 10</td><td>Presidents Day, MLK Day, Memori Thanksgiving Day and Ch Billed as incurred where Fuel Bil WITHIN 90 D/ II WITHIN 90 D/</td><td>al Day, Independence Day, Labor Day, ristmas Day required by law NOTES led As Incurred N/A N/A N/A N/A NOTES NCLUDED AYS OF EMPLOYMENT NCLUDED NOTES IO COST TO EMPLOYEE</td></td<>	New Year's Day, R New Year's Day, R Null BILLING 15,600.00 16,600.00 16,600.00 17,000 18,000 19,000 19,000 10	Presidents Day, MLK Day, Memori Thanksgiving Day and Ch Billed as incurred where Fuel Bil WITHIN 90 D/ II WITHIN 90 D/	al Day, Independence Day, Labor Day, ristmas Day required by law NOTES led As Incurred N/A N/A N/A N/A NOTES NCLUDED AYS OF EMPLOYMENT NCLUDED NOTES IO COST TO EMPLOYEE	
HOLIDAY PREM SICK PA SECTION 5: VEHICLES VEHICLE TYPE PATROL VEHICLE GOLF CART BICYCLE SECTION 6: TRAINING TR PRE-ASSIGNI CPR, FIRST CONTINUIN SECTION 7: UNIFORMS, EQUIPMENT	IUM PAY Y TOTALS: AINING TYPE MENT/BASIC TR/ AID, & AED TRAI G/OTHER EDUC/ AND OTHER ITEM IFFICE RENT OFFICE SUPPLIE:	QUANTITY 1 0 1 AINING NING ATION	\$ - \$ - \$ UNIT COST UNIT COST \$ 1,300.00 \$ - \$ 1,300.00	 \$ - \$ - \$ - \$ - \$ 1,300.00 \$ - \$ 1,300.00 \$ - \$ 1,300.00 \$ - -	New Year's Day, R ANNUAL BILLING \$ 15,600.00 \$	residents Day, MLK Day, Memori Thanksgiving Day and Ch Billed as incurred where Fuel Bil WITHIN 90 D/ II WITHIN 90 D/ II	al Day, Independence Day, Labor Day, ristmas Day required by law NOTES led As Incurred N/A N/A N/A N/A NOTES NCLUDED AYS OF EMPLOYMENT NCLUDED NOTES NOTES	
HOLIDAY PREM SICK PA SECTION 5: VEHICLES VEHICLE TYPE PATROL VEHICLE GOLF CART BICYCLE SECTION 6: TRAINING TR PRE-ASSIGNI CPR, FIRST CONTINUIN SECTION 7: UNIFORMS, EQUIPMENT	IUM PAY Y TOTALS: AINING TYPE MENT/BASIC TR/ AID, & AED TRAI G/OTHER EDUC/ AND OTHER ITEM IFFICE RENT OFFICE SUPPLIE:	QUANTITY 1 0 0 1 AINING NING ATION S S S S S S S S S S S S S	\$ - \$ - \$ UNIT COST UNIT COST \$ 1,300.00 \$ - \$ 1,300.00	\$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ 1,300.00 \$ - \$ 1,300.00 \$ - \$ 1,300.00 \$ - \$ 1,300.00 \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ - \$ 5,558.333 \$ -	New Year's Day, R New Year's Day, R ANNUAL BILLING \$ 15,600.00 \$	residents Day, MLK Day, Memori Thanksgiving Day and Ch Billed as incurred where Fuel Bil WITHIN 90 D/ II WITHIN 90 D/ II	al Day, Independence Day, Labor Day, ristmas Day required by law NOTES led As Incurred N/A N/A N/A NOTES NCLUDED AYS OF EMPLOYMENT NCLUDED NOTES NOTES NO COST TO EMPLOYEE NCLUDED	
HOLIDAY PREM SICK PA SECTION 5: VEHICLES VEHICLE TYPE PATROL VEHICLE GOLF CART BICYCLE SECTION 6: TRAINING TR PRE-ASSIGNI CPR, FIRST CONTINUIN SECTION 7: UNIFORMS, EQUIPMENT	IUM PAY Y TOTALS: AINING TYPE MENT/BASIC TR/ AID, & AED TRAI G/OTHER EDUC/ AND OTHER ITEM DIFFICE RENT OFFICE SUPPLIES E-EMPLOYMENT	QUANTITY 1 0 0 1 AINING NING ATION S S S S S S S S S S S S S	\$ - \$ - \$ UNIT COST UNIT COST \$ 1,300.00 \$ - \$ 1,300.00	 \$ - \$ - \$ - \$ 1,300.00 \$ - \$ 1,300.00 \$ - \$ 1,300.00 \$ - \$ 1,300.00 \$ \$ - > - > - -	New Year's Day, f ANNUAL BILLING 15,600.00 16,600.00 17,700 18,000 19,000 10,000 10,000 10,000 10,000 10,000 10,000 <td>residents Day, MLK Day, Memori Thanksgiving Day and Ch Billed as incurred where Fuel Bil WITHIN 90 D/ II WITHIN 90 D/ II</td> <td>al Day, Independence Day, Labor Day, ristmas Day required by law NOTES led As Incurred N/A N/A N/A NOTES NCLUDED NOTES NOCLUDED NOTES NO COST TO EMPLOYEE NCLUDED NCLUDED NCLUDED</td>	residents Day, MLK Day, Memori Thanksgiving Day and Ch Billed as incurred where Fuel Bil WITHIN 90 D/ II WITHIN 90 D/ II	al Day, Independence Day, Labor Day, ristmas Day required by law NOTES led As Incurred N/A N/A N/A NOTES NCLUDED NOTES NOCLUDED NOTES NO COST TO EMPLOYEE NCLUDED NCLUDED NCLUDED	
HOLIDAY PREM SICK PA SECTION 5: VEHICLES VEHICLE TYPE PATROL VEHICLE GOLF CART BICYCLE SECTION 6: TRAINING TR PRE-ASSIGNI CPR, FIRST CONTINUIN SECTION 7: UNIFORMS, EQUIPMENT	IUM PAY Y TOTALS: AINING TYPE MENT/BASIC TR/ AID, & AED TRAI G/OTHER EDUC/ AND OTHER ITEM DIFFICE RENT OFFICE SUPPLIES E-EMPLOYMENT	QUANTITY 1 0 0 1 AINING NING ATION S S S S S S S S S S S S S	\$ - \$ - \$ - UNIT COST UNIT COST UNIT COST	 \$ - \$ - \$ - \$ 1,300.00 \$ - \$ 1,300.00 \$ - \$ 1,300.00 \$ - \$ 1,300.00 \$ \$ - > - > - -	New Year's Day, R I I BILLING \$ 15,600.00 \$ 5 15,600.00 \$	residents Day, MLK Day, Memori Thanksgiving Day and Ch Billed as incurred where Fuel Bil WITHIN 90 D/ II WITHIN 90 D/ II	al Day, Independence Day, Labor Day, ristmas Day required by law NOTES led As Incurred N/A N/A N/A NOTES NCLUDED NOTES NOCLUDED NOTES NO COST TO EMPLOYEE NCLUDED NCLUDED	
HOLIDAY PREM SICK PA SECTION 5: VEHICLES VEHICLE TYPE PATROL VEHICLE GOLF CART BICYCLE SECTION 6: TRAINING TR PRE-ASSIGNI CPR, FIRST CONTINUIN SECTION 7: UNIFORMS, EQUIPMENT	IUM PAY Y TOTALS: AINING TYPE MENT/BASIC TR/ AID, & AED TRAI G/OTHER EDUC/ AND OTHER ITEM DIFFICE RENT OFFICE SUPPLIES E-EMPLOYMENT	QUANTITY 1 0 0 1 AINING NING ATION S S S S S S S S S S S S S	\$ - \$ - \$ UNIT COST UNIT COST UNIT COST UNIT COST UNIT COST UNIT COST TOTALS:	 \$ - \$ - \$ - \$ 1,300.00 \$ - \$ 1,300.00 \$ - \$ 1,300.00 \$ - \$ 1,300.00 \$ \$ - > - > - -	New Year's Day, P	residents Day, MLK Day, Memori Thanksgiving Day and Ch Billed as incurred where Fuel Bil WITHIN 90 D/ III WITHIN 90 D/ III III III III	al Day, Independence Day, Labor Day, ristmas Day required by law NOTES Ied As Incurred N/A N/A N/A N/A NOTES NOTES NOLUDED NOTES NO COST TO EMPLOYMENT NCLUDED NCLUDED NCLUDED NCLUDED N/A N/A	

NOTE: <u>Not</u> included are Holiday /Extra Coverage Costs, Special Event Coverage, Off-Duty Police Coverage, Rent and any other expenses not shown above. Should these items be required, the cost will be billed separately. Salaried positions are shown as annual cost figures billed on 52 weeks billing inclusive of any PTO.

\$

12,550.31 \$

54,384.66

\$

652,615.96

DIVERSIFIED UNDERGROUND INC.

August 1, 2022

2nd Notice of Rate Increase

Dear Valued Customer,

In the past few years, Diversified Underground has seen ever-increasing costs for supplies, fuel, etc. that has affected the cost of providing service to our customers.

Diversified Underground has always operated under the idea that we will provide top quality level service at a very competitive price. In staying true to that, we have not increased the cost of our service even though the cost of supplies & labor has dramatically changed over the last few years.

As we continue to improve our service, operations, and support to our customers, we must also manage the industry wide cost increases on raw material, labor, insurance, and fuel.

Starting August 1st, 2022, we will be increasing our rates by 20% to cover our costs of service.

We understand that a price increase is not convenient, and we want to thank you for understanding that it is necessary for us to maintain the services we provide. We continue to invest in our company, employees, and resources to make every effort to be your preferred vendor.

We greatly appreciate your loyalty and look forward to many more years serving you.

If you have any questions or concerns, please don't hesitate to contact us.

Best Regards,

Mark Allen General Manager



2300 Cavanaugh Road Watkins CO, 80137


PHONE: (303) 636-9999 (303) 671-8728 FAX WEB SITE http://www.diversifiedunderground.com

Parcel Description (PROVIDED BY CLIENT)

PARCELS OF LAND, LOCATED IN THE SOUTH HALF OF SECTION 19, TOWNSHIP 5 SOUTH, RANGE 65 WEST OF THE 6TH P.M., CITY OF AURORA, COUNTY OF ARAPAHOE, STATE OF COLORADO.


Legend

•	FOUND MONUMENT AS DESCRIBED
\oplus	FOUND BRASS TAG AS DESCRIBED
	CONCRETE
	EDGE OF ASPHALT
xx	FENCE
-o	GUARDRAIL
0	SIGN
\otimes	BOLLARD
ж хус	FIRE HYDRANT
Ň	WATER VALVE
\bigotimes	WATER MANHOLE
۲۳٫× ۲۳/۲'	DECIDUOUS TREE (TRUNK DIAMETER/DRIP LINE RADIUS)
₩ ×"/×'	CONIFEROUS TREE (TRUNK DIAMETER/DRIP LINE RADIUS)
	IRRIGATION VALVE
——е—	ELECTRIC LINE
\boxtimes	TRANSFORMER
EM	ELECTRIC METER
EP	ELECTRICAL PANEL
EV	ELECTRIC VAULT
¢	LIGHT POLE
\diamond	DECORATIVE LIGHT
OVU	OVERHEAD UTILITY LINE
\bigcirc	CABLE TV MANHOLE
F0	FIBEROPTIC LINE
FOV	FIBEROPTIC VAULT
G	GAS LINE
V	UNIDENTIFIED VAULT
ELEV	ELEVATION
INV	INVERT
CCP	CONCRETE PIPE



Notes


- 1. THIS EXHIBIT WAS PREPARED WITHOUT THE BENEFIT OF A CURRENT TITLE COMMITMENT AND DOES NOT CONSTITUTE A TITLE SEARCH BY FLATIRONS, INC. TO DETERMINE TITLE OR EASEMENTS OF RECORD. THIS EXHIBIT DOES NOT PURPORT TO REFLECT ANY OF THE FOLLOWING WHICH MAY BE APPLICABLE TO THE SUBJECT REAL ESTATE: EASEMENTS, OTHER THAN POSSIBLE EASEMENTS THAT WERE VISIBLE AT THE TIME OF MAKING THIS EXHIBIT: BUILDING SETBACK LINES; RESTRICTIVE COVENANTS; SUBDIVISION RESTRICTIONS; ZONING OR OTHER LAND-USE REGULATIONS; AND ANY OTHER FACTS THAT AN ACCURATE AND CURRENT TITLE SEARCH MAY DISCLOSE.
- 2. ACCORDING TO COLORADO LAW, YOU MUST COMMENCE ANY LEGAL ACTION BASED UPON ANY DEFECT IN THIS EXHIBIT WITHIN THREE YEARS AFTER YOU FIRST DISCOVER SUCH DEFECT. IN NO EVENT MAY ANY ACTION BASED UPON ANY DEFECT IN THIS EXHIBIT BE COMMENCED MORE THAN TEN YEARS FROM THE DATE OF THE CERTIFICATION SHOWN HEREON.
- 3. THIS EXHIBIT WAS PREPARED FOR THE EXCLUSIVE USE OF COLLINS ENGINEERS & SOUTHLANDS METROPOLITAN DISTRICT NO. 1, NAMED IN THE STATEMENT HEREON. SAID STATEMENT DOES NOT EXTEND TO ANY UNNAMED PERSON WITHOUT AN EXPRESS STATEMENT BY THE SURVEYOR NAMING SAID PERSON.
- 4. THIS EXHIBIT IS VALID ONLY IF PRINT HAS SEAL AND SIGNATURE OF SURVEYOR.
- 5. SOURCE INFORMATION FROM PLANS AND MARKINGS HAVE BEEN COMBINED WITH OBSERVED EVIDENCE OF UTILITIES TO DEVELOP A VIEW OF THOSE UNDERGROUND UTILITIES. HOWEVER LACKING EXCAVATION, THE EXACT LOCATION OF UNDERGROUND FEATURES CANNOT BE ACCURATELY, COMPLETELY AND RELIABLY DEPICTED. WHERE ADDITIONAL OR MORE DETAILED INFORMATION IS REQUIRED. THE CLIENT IS ADVISED THAT EXCAVATION MAY BE NECESSARY. NO EXCAVATIONS WERE MADE DURING THE PROGRESS OF THIS EXHIBIT TO LOCATE BURIED UTILITIES AND STRUCTURES. ALL UNDERGROUND UTILITIES MUST BE FIELD LOCATED BY THE APPROPRIATE AGENCY OR UTILITY COMPANY PRIOR TO ANY EXCAVATION, PURSUANT TO C.R.S. SEC. 9-1.5-103.
- 6. THE DISTANCE MEASUREMENTS SHOWN HEREON ARE U.S. SURVEY FOOT.
- 7. THE CONTOURS REPRESENTED HEREON WERE INTERPOLATED BY AUTOCAD CIVIL 3D (DIGITAL TERRAIN MODELING) SOFTWARE BETWEEN ACTUAL MEASURED SPOT ELEVATIONS. DEPENDING ON THE DISTANCE FROM A MEASURED SPOT ELEVATION AND LOCAL VARIATIONS IN TOPOGRAPHY, THE CONTOUR SHOWN MAY NOT BE AN EXACT REPRESENTATION OF THE SITE TOPOGRAPHY. THE PURPOSE OF THIS TOPOGRAPHIC MAP IS FOR SITE EVALUATION AND TO SHOW SURFACE DRAINAGE FEATURES. ADDITIONAL TOPOGRAPHIC OBSERVATIONS MAY BE NECESSARY IN SPECIFIC AREAS OF DESIGN. TOPOGRAPHY SHOWN HEREON COMPLIES WITH NATIONAL MAP ACCURACY STANDARDS.
- 8. BENCHMARK INFORMATION: SMARTNET NORTH AMERICA CONTINUOUSLY OPERATING REFERENCE STATIONS (CORS) NETWORK WAS USED TO ESTABLISH A GPS DERIVED ELEVATION ON AN ON-SITE BENCHMARK AT THE NORTHWEST CORNER OF LOT 16, BLOCK 1 BEING A FOUND 0.75" BRASS TAG STAMPED "CLC LS 24670" WITH AN ELEVATION OF 6074.88 FEET (NAVD 88). CITY OF AURORA POINT 5S6519SW001, BEING A 3" BRASS CAP STAMPED "COA BM, SLP-125.5, 2005" LOCATED 0.1 MILES NORTHWEST OF THE SITE, WITH A PUBLISHED ELEVATION OF 6067.60 FEET, WAS CHECKED INTO WITH AN AS-MEASURED ELEVATION OF 6067.60 FEET. NO DIFFERENTIAL LEVELING WAS PERFORMED TO ESTABLISH THE ELEVATION OF THE ON-SITE BENCHMARK.
- 9. DATES OF FIELDWORK: 07/06/2022 (CREW CHIEF A. NICHOLSON)
- 10. BOUNDARY DETERMINATION IS NOT A PART OF THIS EXHIBIT. THIS IS NOT A "LAND SURVEY PLAT" OR "IMPROVEMENT SURVEY PLAT" AND THIS EXHIBIT IS NOT INTENDED FOR PURPOSES OF TRANSFER OF TITLE OR SUBDIVISIONS OF LAND AND THAT IT IS NOT TO BE RELIED UPON FOR THE ESTABLISHMENT OF A FENCE, BUILDING OR OTHER FUTURE IMPROVEMENT LINES. PARCEL LINES SHOWN HEREON ARE FOR INFORMATIONAL PURPOSES ONLY AND ARE DRAWN FROM RECORD INFORMATION AVAILABLE DURING THE PREPARATION OF THIS EXHIBIT. AN IMPROVEMENT SURVEY PLAT IS RECOMMENDED TO DEPICT MORE PRECISELY THE LOCATIONS OF THE IMPROVEMENTS SHOWN HEREON.
- 11. ALL WALLS SHOWN ARE MADE OF CONCRETE BLOCKS AND ARE 1 FOOT WIDE.






JAMES Z. GOWAN, A LAND SURVEYOR LICENSED IN THE STATE OF COLORADO, HEREBY STATE FOR AND ON BEHALF OF FLATIRONS, INC., TO COLLINS ENGINEERS & SOUTHLANDS METROPOLITAN DISTRICT NO. 1, THAT THIS TOPOGRAPHIC EXHIBIT WAS PREPARED BY ME OR UNDER MY RESPONSIBLE CHARGE, IS IN ACCORDANCE WITH APPLICABLE STANDARDS OF PRACTICE AND IS NOT A GUARANTY OR WARRANTY, EITHER EXPRESSED OR IMPLIED. SAID EXHIBIT AND THE RELATIVE ELEVATIONS SHOWN HEREON ARE ACCURATE TO THE BEST OF MY KNOWLEDGE, INFORMATION AND BELIEF.

JAMES Z. GOWAN COLORADO P.L.S. #29038 VICE PRESIDENT, FLATIRONS, INC.








SOUTHLANDS MALL WALLS PROJECT TOPOGRAPHIC EXHIBIT


A PARCEL OF LAND, LOCATED IN THE SOUTH HALF OF SECTION 19, TOWNSHIP 5 SOUTH, RANGE 65 WEST OF THE 6TH P.M., CITY OF AURORA, COUNTY OF ARAPAHOE, STATE OF COLORADO SHEET 2 OF 5

FOUND #5 REBAR WITH A —/ YELLOW PLASTIC CAP "ILLEGIBLE"









JECT	REVISION DATE
	TOPOGRAPHIC EXHIBIT PREPARED FOR PREPARED FOR COLLINS ENGINEERS & SOUTHLANDS METROPOLITAN DISTRICT NO. 1 METROPOLITAN DISTRICT NO. 1 COPYRIGHT 2022 FLATRONS, INC.
	Flatirons, Inc. Land Surveying Services www.FlatironsInc.com655 FOURTH AVE LONGMONT, CO 80501 PH: (303) 776-17333825 IRIS AVE, STE 395 BOULDER, CO 80301 PH: (303) 443-98304501 LOGAN ST. BENVER, CO 80216 PH: (303) 926-6997 PH: (303) 923-3180
	JUE C JUE C JU

Wall Inspection Report

Structure ID#: Southlands Mall - Bottom Wall

Owner:	Private
Maintained By:	Private
Main Structure Type:	25 - Soil Nail
Location:	E Smoky Hill b/wn Main & Aurora
Service Type-Carried:	J - Slope - Talus
Service Type-In Front:	U - Other
Inspection Frequency:	12 months

Inspection Date: 2022-07-07

Year Built: Region/Section:	
	10.050
Start of Wall MP:	10.656
Route:	470B
Features Carried:	E. Smoky Hill Rd.
Features In Front:	Commercial
Wall Risk:	
Essentia	al Repair Finding

Inspection Scopes: NBI X Element Underwater Other Inspection Type: 4 - Special



Elevation looking southeast

OVERALL RATINGS	Inspection Team	Agenc	y
Main Structure: 7	Danny Debes - Team Lead	er Collins	Engineers
Foundation: <u>N</u> Channel & Channel Protection: <u>N</u>	_Jack Summers - Team Mer	nber Collins	Engineers
		Inspec	tion Resources
Project:	Southland Mall- Ret. Wall INSP	Crew Hours _	
Project Number:		Flagger Hours _	
Temperature:	050 5	Helper Hours _	
·		Snooper Hours _	
Weather Conditions:	Sunny	Special Crew Hours _	
		Special Equipment Hours _	0.0
Access Issues:	Animals 3rd Party Fer	ncing 🗌 Other:	

Wall Inspection Report

Structure ID#: Southlands Mall - Bottom Wall

Inspection Date: 2022-07-07

7 Features In FrontCommercial60 FoundationN - No8 Structure ID NumberR470B010656RRA61 Channel & Channel ProtectionN - No8A Structure Number71 Water AdequacyN - No	
2EM Region/Maint Section 05 Arraphoe 05 Curb or Sidewalk. In Front(R) 3 Numericary Rei (20/uh Front) 1 - Inventory Rite Carried 50 Curb or Sidewalk. In Front(R) 51 Wirentory Rei (20/uh Front) 1 - Inventory Rite Carried 51 With Curb-o-Curb, Carried 51 Wirentory Rei (20/uh Front) 1 - Inventory Rite Carried 51 With Curb-o-Curb, Carried 52 Warrage Wall Height 53 Maximum Wall Height 52 56 Ecurb or Sidewalk. In Front(R) 53 Maximum Wall Height 53 56 Ecurb or Sidewalk. In Front(R) 54 Minimum Wall Height 54 57 Features Carried E. Smoky Hill Riv 54 Minimum Wall Height 56 58 Structure Number R47020010567RA 7 Features Protection N - N 18 Structure Namber 2 Sign of Wall Elevation N - N 7 11 Refore Wall Keight 39355319 3955911 393 938 938 948 948 12 Lastide Eard-VWall 39355319 395591743 39560743 </td <td>100'</td>	100'
3 County Code 005 Araphae 4 Place Code 0400 0400 NURORA 5A Inventory Rte (Colin Front) 1 Inventory Rte (Cisigning) 50 Curb or Sidewalk. In Front(L) 5A Inventory Rte (Cisigning) 51 Status Status Status 5D Inventory Rte (Cisigning) 52 Avarage Valle Neght Status 5D Inventory Rte (Cisigning) 53 Status Status Status 5D Inventory Rte (Cisigning) 53 Status Status <td>100'</td>	100'
4 Piace Code 04000 - AURORA 50D Curb or Sidewalk, In Front (R) 5A Inventory Rie (Only Front) 1 - Inventory Rie Carried 51 Width Curb-Outh, Carried 5B Inventory Rie (LO.S.) 53 Maximum Wall Height 53 Maximum Wall Height 5C Inventory Rie (CD.S.) 53 Maximum Wall Height 53 Maximum Wall Height 5E Inventory Rie (CD.S.) 53 Maximum Wall Height 7 - Gox 7 Features In Front Commercial 60 Foundation N - Ni 8 Structure Number R70B010660RRA 71 Water Adequacy N - Ni 9 Location E Smoky Hill Livin Main & Aurora 90 Inspection Date 91 Froquency 11 Reference Point 39356319 39.569611 922 Cri If Feat Insp - Underwater N - Ni 12 Baset My Network 93361743 39.60046 984 Border Wall State Code 994 Border Wall State Code 17 Longlude Start-of-Wall 104422225 104.70618 984 Border Wall State Code 984 Border Wall State Code 17 Longlude Start-of-Wall 104423206 -104.71057 98 Border Wall Structure # 984 Border Wall Structure # 18 Attrust Responsibility 100 STRAHNET Hwy Designation 104	000'
5A Inventory Rte (Stange) 51 Virdit Curb-GCurb, In Front 5B Inventory Rte (IS Re Num) 52 Average Wall Height 5D Inventory Rte (IR R Num) 52 Average Wall Height 5E Inventory Rte (IR R Num) 53 Maximum Wall Height 56 Features Carried E. Smoky Hill Rd. 60 Features In Front Commercial 7 Features In Front Commercial 60 Features Adequacy N - Nu 8 Structure ID Number E Smoky Hill Du'm Main & Aurora 90 Inspection Date 90 N Nu 12 Base Hoy Network 39355319 39.59611 392 CR Feat Insp - Special 292 CR Feat Insp - Special 292 CR Feat Insp - Special 292 CR Feat Insp - Special 293 292 CR Feat Insp - Vadewater 292 292 CR Feat Insp - Special 293 293 293 293 293 293 <td>000'</td>	000'
5B Inventory Rte (D.S.) 5C Inventory Rte (Rte Num) 5E Inventory Rte (D.S.) 6 Structure Scareid 7 Features Carried 8 Structure Number 8 Structure Number 9 Location 1 Reference Point 12 Base Hwy Network 13 LRS Inventory & Subroute # 16 Latitude End-of-Wall 39355319 17 Longitude End-of-Wall 39361743 18 Start of Wall Elevation 104422225 17 Longitude End-of-Wall 104422225 10 Tolongitude Start-of-Wall 10442225 17 Longitude End-of-Wall 104423806 18 Range 100 18 Torogitude Start-of-Wall 10442225 19 Border Wall Starte Code 20 Start Mail Elevation 104 18 Range 100 STRAHNET Hwy Desi	0350'
5C Inventory Rte (RL Num) 52 Average Wall Height 5E Inventory Rte (Rte Num) 53 Maximum Wall Height 6E Features Carried E. Smoky Hill Rd. 54 Main Structure 7 - Got 7 Features In Front Commercial 60 Foundation N - Nu 8 Structure ID Number FA70B0106568RA 01 N - Nu 9 Location E Smoky Hill D/wn Main & Aurora 90 Inspection Date 91 Frequency 92 Crift Feat Insp - Special 928 Crift Feat Insp - Special 935 935 93 936 90468 935 935 90469 935 935 90469 935 936 90468 935 936 90468 935 936 90468 935 936 90468 935 936 90468 935 936 90468 935 936 90468 935 936 90468 935 936 90468 935 936 90468 935 936 90468 935 936 90468 935 936 90468 935 936 90468 935 936 90468 936 936	0000'
5D Inventory Rte (Re Num) 53 Maximum Wall Height 5E Inventory Rte (Dr Suffix) 54 Minimum Wall Height 57 Features Carried E. Smoky Hill Rd. 58 Main Structure 7-Got 7 Features In Front Commercial 60 Foundation N - Nc 8 Structure ID Number R47260/0666RRA N - Nc N N 9 Location E Smoky Hill D/wn Main & Aurora 70 Y2 Adjacent Roadway Alignment N - Nc 10 Reference Point Bistructure Mumber 3955319 39.59611 395.016 398 Underwater 922 Crit Feat Insp - Opecial 922 Structure Meanset Inspection Date 398	9.00000'
55 Inventory Rie (Dir Suffix)	0013'
6 Features Carried E. Smoky Hill Rd. Commercial 68 Main Structure 7 - Got 7 Features In Front Commercial 60 Foundation N - Nc 8 Structure Number R4708010656RRA 61 Channel & Channel A Channel Protection N - Nc 8 Structure Number ESmoky Hill D/wn Main & Aurora 61 Channel & Channel & Channel A Channel Protection N - Nc 9 Location E Smoky Hill D/wn Main & Aurora 91 Frequency N - Nc 12 Base Hwy Network 91 Frequency 92B Crit Feat Insp - Underwater 92C Crit Feat Insp - Underwater 14 Latitude Start-of-Wall 3935319 39.59211 938 Underwater Inspection Date 938 Undered Wall State Code 938 Detroer Wall State Code 998 Border Wall State Code 998 Border Wall State Code 94 Higtevalon 100422225 104.70167 998 Border Wall State Code 998 Derder Wall State Code 91 Regretor Nambip 100 Stractors Type 100 Stractors Type 100 Stractors 101 Stractors 103 Temp Structure Designation 104 Highway System 105 Year Reconstructe 4 107 Vericial Supports Type	0000'
7 Features In Front Commercial 60 Foundation N - Nc 8 Structure Number R470B010656RRA 61 Channel & Channel Protection N - Nc 9 Location E Smoky Hill Elwn Main & Aurora 71 Water Adequacy N - Nc 9 Location E Smoky Hill Elwn Main & Aurora 71 Water Adequacy N - Nc 12 Base Hwy Network 91 Frequency 24 Algoent Radway Alignment N - Nc 13 LRS Inventory & Subroute # 93055319 3955319 3956004 920 Crit Feat Insp - Underwater 920 Crit Feat Insp - Underwater 920 Crit Feat Insp - Underwater 930 Special Inspection Date 930 930 Bunderwater Inspection Date 930 Special Inspection Date 930 930 930 930 Paceron Responsibility 100 100 Traffic 100 100 Traffic 100 100 Traffic 100 100 100 100 100 100 100 100 100 100	od Condition
8 Structure ID Number R470B010656RRA 61 Channel Protection N - Nc 8A Structure Number E Structure Number N - Nc 9 Location E Structure Number N - Nc 11 Reference Point 9 Location N - Nc 12 Base Hwy Network 9 Location N - Nc 13 LRS Inventory & Subroute # 9355319 39.59811 99.58319 99.58319 16A Latitude Start-of-Wall 393561743 39.60048 93.55921 199.792 92.0711 Features 99.202 104.070618 99.80467 Wall Starto-Code 99.80467 Wall Starto-Wall 104.422225 -104.70618 99.80467 Wall Starto-Code 99.80467 Wall Starto-Code 99.80467 Wall Starto-Wall 104.422806 -104.71067 99.80467 Wall Starto-Code 99.80467 Wall Starto-Wall 100.57141 90.80467 Wall Starto-Wall 100.57141 90.572141 90.572141 100	ot Applicable
8A Structure Number 71 Water Adequacy N - Nc 9 Location E Smoky Hill blwn Main & Aurcra 72 Adjacent Roadway Alignment N - Nc 12 Base Hwy Network 91 Frequency 928 Crif Feat Insp - Underwater 9926 Crif Feat Insp - Underwater 13 LRS Inventory & Subroute # 93255319 39.6004 938 Underwater Inspection Date 9926 Crif Feat Insp - Special 16A Latitude Start-of-Wall 39361743 39.6004 938 Underwater Inspection Date 9928 Crif Feat Insp - Special 17A Longitude Start-of-Wall 104422225 -104.70618 988 Border Wall State Code 988 Border Wall State Code 17A Longitude Start-of-Wall 104422306 -104.71067 99 Border Wall State Code 988 Border Wall State Code 18A Range 1044223006 -104.71067 99 Border Wall State Code 988 Dorder Wall State Code 988 Dorder Wall State Code 19B Township 102 Direction of Traffic 103 Term Structure Designation 102 Direction of Traffic 103 Term Structure Designation 104 Highway System 105 Federal Lands Highway 104 Highway System 105 Federal Lands Highway 114 Future ADT 125Ch Type of Walls 125Ch Type of Walls 125Ch Type of Walls 125Ch Type of Walls 124 Start Corried 13	ot Applicable
9 Location E Smoky Hill b/wn Main & Aurora 72 24 djacent Roadway Alignment N - Nc 11 Reference Point 90 Inspection Date 91 Frequency 92B Crit Feat Insp - Underwater 92B 22B 22B 22B 22C Crit Feat Insp - Special 93B 93B 93B 93B 93B 93B 94D 93B 93B </td <td>ot Applicable</td>	ot Applicable
11 Reference Point 90 Inspection Date 12 Base Hwy Network 91 Frequency 13 LRS Inventory & Subroute # 92 Crit Feat Insp - Underwater 16 Latitude Start-of-Wall 39355319 39.509811 17A Longitude End-of-Wall 39361743 39.60044 18B Start of Wall Elevation 104422225 -104.70618 17A Longitude End-of-Wall 104423206 -104.706179 18B Township 104423206 -104.706179 18B Township 104423206 -104.70618 18C Township 100 Stracture # 10A Traffic 103 Traffic 10B Township 100 Stracture # 20 Toil 103 Temp Structure Designation 104 Highway 106 Year Reconstructed 20 Forder Number 109 Truck ADT 23E Uncorral Class 114 Future ADT 24F Pr	ot Applicable
12 Base Hwy Network 91 Frequency 13 LRS Inventory & Subroute # 92 Crit Feat Insp - Underwater 14 Latitude End-of-Wall 39361743 39.60048 16 Start of Wall Elevation 932 Special Inspection Date 17 Longitude End-of-Wall 10442225 -104.70618 17A Longitude End-of-Wall 10442225 -104.70618 17B End of Wall Elevation 104422306 -104.71057 17B Brod Wall Elevation 98 Border Wall State Code 18A Range 100 STRAHNET Hwy Designation 102 Direction of Traffic 100 STRAHNET Hwy Designation 103 State Count Number 100 STRAHNET Hwy Designation 20 Orig Project Number 100 Forequency 23 Orig Project Number 100 Forequency 24 Maint. Responsibility 106 Forequency 23 Orig Project Number 107 Yetical Supports Type 23 Orig Proj	2022-07-07
13 LRS Inventory & Subroute # 16 Latitude Start-of-Wall 39355319 39.598111 16 Latitude End-of-Wall 39361743 39.60048 17 Longitude End-of-Wall 104422225 -104.70618 17 Longitude End-of-Wall 1044223806 -104.71057 178 End of Wall Elevation 104423806 -104.71057 188 Forwnship 10423806 -104.71057 188 Forwnship 102 Direction of Traffic 100 STRAHNET Hwy Designation 102 101 2Direction of Traffic 103 Temp Structure Designation 102 Direction of Traffic 104 Highway System 20 Oig Project Number 100 Strganzed National Network 23 Gig Project Number 109 Truck ADT 24E Project Indicator 113 Scour Officional Walls 27 Year Built 114 Future ADT 29 Avareage Daily Traffic 125 CD Type of Wall Rail on Top 31 Inventory Route Median 2 - Closed Median (no barrier) 36	12 m
16 Latitude Start-of-Wall 39355319 39.59814 16 Latitude End-of-Wall 39361743 39.60044 17 Longitude Start-of-Wall 104422225 -104.70618 17 Longitude End-of-Wall 104422225 -104.70618 17 Longitude End-of-Wall 104422225 -104.70618 178 End of Wall Elevation 98 Percent Responsibility 99 Border Wall Structure # 99 90 188 Township 100 STRAHNET Hwy Designation 182 Section 100 STRAHNET Hwy Designation 19 Bypass Detour Length 100 STRAHNET Hwy Designation 20 Toirg Project Number 100 STRAHNET Hwy Designation 21 Maint. Responsibility 100 STRAHNET Hwy Designation 22 Orig Project Number 100 STRAHNET Hwy Designation 23 Drig Project Number 100 Structure Designation 24 Maint. Responsibility 101 101 Heid Hwain 25	12 111
16A Latitude End-of-Wall 39361743 39.60048 17B Longitude Start-OrWall 104422225 -104.70618 17A Longitude End-of-Wall 104422306 -104.70618 17B End of Wall Elevation 104423306 -104.71057 17B End of Wall Elevation 104423306 -104.71057 17B End of Wall Elevation 99B Percent Responsibility 18B Township 99 DoTRe/HNET Hwy Designation 18B Township 103 Temp Structure # 20 Toll 104 Highway 21 Maint. Responsibility 105 Federal Lands Highway 22 Owner 107 Vertical Supports Type 23. Orig Project Indicator 107 Vertical Walls 24. Lanes in Front 000 109 Truck ADT 25 AB Type of Wall Rail on Top 2- Closed Median (no barrier) 135 Mil Stare Code 36M Hail Height. On Top NNNN 1438 Min Dist Fr Route, Carried 136 Milaege Log Section Letter 37 Historical Significance J- Slope - Talus 1438 Win Dist Fr Route, In Front	
16B Start of Wall Elevation 93C Special Inspection Date 17A Longitude Start-of-Wall 104423225 -104.70618 98A Border Wall State Code 17B End of Wall Elevation 104423806 -104.71057 98A Border Wall State Code 18B Township 10423806 -104.71057 99B Border Wall State Code 18B Township 100 State Adapted State Code 100 State Code 18B Township 100 State Adapted State Code 100 State Code 20 Form 100 State Adapted State Code 100 State Code 100 101 101 100 State Code 100 State Code 100 104 105 Federal Lands Highway 100 104 Fighway System 105 Federal Lands Highway 105 Federal Lands Highway 106 107 Vertical Supports Type 109 109 Truck ADT 110 Designated National Network 113 Suca Code Highway 110 104 114 <future adt<="" td=""> 115 Year of ADT 115 Year of ADT 115 Year of ADT</future>	
17 Longitude Start-of-Wall 104422225 -104.70618 17A Longitude End-of-Wall 104422306 -104.71057 17B End of Wall Elevation 99 Border Wall State Code 18A Range 99 Border Wall Structure # 18B Township 99 Border Wall Structure # 18C Section 102 Direction of Traffic 19 Bypass Detour Length 103 Temp Structure Designation 20 Toll 104 Highway 105 21 Maint. Responsibility 106 Year Constructed 107 22 Owner 107 Vertical Supports Type 108 23E Subaccount Number 110 Designated National Network 23Es Discount Number 110 110 Designated National Network 23Es Lanes on Structure 06 125AB Type of Wall Rail in Front 113 24 Average Daily Traffic 133 136 Mileage Log Section Letter 136 36AD Traffic Safety Features on Top NNINN NNINN Avg Dist Fr	
17A Longitude End-of-Wall 104423806 -104.71057 17B End of Wall Elevation 98B Percent Responsibility 18A Range 100 STRAHNET Hwy Designation 18B Township 102 Direction of Traffic 18C Section 103 Term Structure Designation 19 Bypass Detour Length 105 Federal Lands Highway 20 Toll 105 Federal Lands Highway 21 Maint. Responsibility 105 Federal Lands Highway 22 Orig Project Number 109 Truck ADT 23E Subaccount Number 109 Truck ADT 23E Functional Class 110 Designated National Network 23E Functional Class 114 Future ADT 27 Year Built 115 Year of Future ADT 28 Lanes on Structure 06 125/AB Type of Wall Rail in Top 24 Lanes on Structure 02 133 Special Insp. Equipment 136 30 Year of ADT 133 Special Insp. Equipment 136	
17B End of Wall Elevation 99 Border Wall Structue # 18A Range 100 STRAHNET Hwy Designation 18B Township 102 Direction of Traffic 18C Section 103 Temp Structure Designation 19 Bypass Detour Length 104 Highway System 20 Toll 105 Federal Lands Highway 21 Maint. Responsibility 106 Year Reconstructed 22 Owner 107 Vertical Supports Type 23E Project Indicator 110 Designated National Network 23E Functional Class 110 Designated National Network 23E Functional Class 113 Scour Critical Walls 24 Lanes In Front 001 125CD Type of Wall Rail on Top 25 Average Daily Traffic 2 Closed Median (no barrier) 133 Special Insp. Equipment 36AD Traffic Safety Features on Top NNNN Xer of ADT 136 Milase Log Section Letter 36H Traffic Safety Features on Top NNNN Xer of Service, On J - Slope -	
18A Range 100 STRAHNET Hwy Designation 18E Township 101 STRAHNET Hwy Designation 18C Section 102 Direction of Traffic 18 Bypass Detour Length 103 Temp Structure Designation 20 Toll 104 Highway System 21 Maint. Responsibility 106 Year Reconstructed 22 Owner 107 Vertical Supports Type 23 Orig Project Number 109 Truck ADT 23E Project Indicator 110 Designated National Network 23E Project Indicator 113 Scour Critical Walls 24 Lanes on Structure 06 25A Lanes on Structure 06 28 Lanes In Front 00 29 Average Daily Traffic 115 Year of Future ADT 213 Inventory Route Median 2 - Closed Median (no barrier) 36AD Traffic Safety Features on Top NNNN 36H Rail Height On Top N* 36H Rail Height On Top N* 37 Historical Significance 1 - Stope - Talus 18 Year of Service, On J - Stope - Talus 19 Froute, In Front 144 Asspeed Limit, Re Carried 37 Historical Significance 1 - Stope/Masonry 47 Tot Horz Clearance, Carried 035 <td></td>	
18B Township 102 Direction of Traffic 18C Section 103 Temp Structure Designation 19 Bypass Detour Length 104 Highway System 20 Toll 105 Federal Lands Highway 21 Maint. Responsibility 106 Year Reconstructed 22 Over 107 Vertical Supports Type 23 Orig Project Number 109 Truck ADT 23E Subaccount Number 110 Designated National Network 23E Froject Indicator 114 Future ADT 236 Functional Class 115 Year of Future ADT 27 Year Built 115 Year of Future ADT 28A Lanes on Structure 06 125CD Type of Wall Rail in Front 29 Average Daily Traffic 133 Special Insp. Equipment 133 Special Insp. Equipment 30 Year of ADT 136 Mileage Log Section Letter 143 Min Dist Fr Route, Carried 36LD Traffic Safety Features in Front NNNN Max Dist Fr Route, In Front Avg Dist Fr Route, In Front	
18C Section 103 Temp Structure Designation 19 Bypass Detour Length 104 Highway System 20 Toll 105 Federal Lands Highway 21 Maint. Responsibility 106 Year Reconstructed 22 Owner 107 Vertical Supports Type 23 Orig Project Number 109 Truck ADT 23E Project Indicator 110 Designated National Network 23EE Froject Indicator 1110 Designated National Network 23E Project Indicator 113 Scour Critical Walls 26 Functional Class 114 Future ADT 27 Year Built 115 Year of Future ADT 28 Lanes on Structure 06 125CD Type of Wall Rail on Top 29 Average Daily Traffic 113 Special Insp. Equipment 133 30 Year of ADT 2 Closed Median (no barrier) 143A Min Dist Fr Route, Carried 36AD Traffic Safety Features on Top NNNN Ang Dist Fr Route, In Front 1438 36H Rai	
19 Bypass Detour Length 104 Highway System 20 Toll 105 Federal Lands Highway 21 Maint. Responsibility 106 Year Reconstructed 22 Owner 107 Vertical Supports Type 23 Orig Project Number 107 Vertical Supports Type 23 Subaccount Number 109 Truck ADT 23E Project Indicator 110 Designated National Network 23E Functional Class 114 Future ADT 27 Year Built 115 Year of Future ADT 28 Lanes on Structure 06 125CD Type of Wall Rail on Top 29 Average Daily Traffic 113 Special Insp. Equipment 133 30 Year of ADT 2 Closed Median (no barrier) 143M kin Dist Fr Route, Carried 36L Traffic Safety Features in Front 2 Closed Median (no barrier) 143B Min Dist Fr Route, In Front 36H Rail Height. On Top N" Avg Dist Fr Route, In Front Avg Dist Fr Route, In Front 36H Traffic Safety Features in Front NNNN Avg	
20 Toll 105 Federal Lands Highway 21 Maint. Responsibility 106 Year Reconstructed 22 Owner 107 Vertical Supports Type 23 Orig Project Number 109 Truck ADT 23E Subaccount Number 109 Designated National Network 23E Project Indicator 110 Designated National Network 23E Project Indicator 113 Scour Critical Walls 24 Functional Class 114 Future ADT 27 Year Built 115 Seare of Wull Rail on Top 28 Lanes on Structure 06 29 Average Daily Traffic 125CD Type of Wall Rail on Top 30 Year of ADT 133 Special Insp. Equipment 31 Inventory Route Median 2 - Closed Median (no barrier) 36H Rail Height. On Top NNNN 36H Rail Height of Rail In Front NNNN 37 Historical Significance 1438 Min Dist Fr Route, Carried 42 Type of Service, On J - Slope - Talus In Front U - Other 43 Wall Face Material 7 - Stone/Masonry Type of Design/Construction 25 - Soil Naii 47 Tot Horz Clearance, In Front 035' 47A Tot Horz Clearance, In Front 035' 47A Tot Horz Clearance,	
21 Maint. Responsibility 106 Year Reconstructed 22 Owner 107 Vertical Supports Type 23 Subaccount Number 109 Truck ADT 23E Project Indicator 110 Designated National Network 23E Project Indicator 111 Scour Critical Walls 26 Functional Class 114 Future ADT 27 Year Built 115 Year of Future ADT 28 Lanes on Structure 06 125CD Type of Wall Rail on Top 28 Lanes In Front 00 125CD Type of Wall Rail in Front 30 Year of ADT 133 Special Insp. Equipment 31 Inventory Route Median 2 - Closed Median (no barrier) 133 Min Dist Fr Route, Carried 36AD Traffic Safety Features on Top N" Avg Dist Fr Route, Carried 1438 Main Dist Fr Route, Carried 36H Rail Height. On Top N" Avg Dist Fr Route, In Front Max Dist Fr Route, In Front 37 Historical Significance 1 - Slope - Talus 144A Speed Limit, Rte Carried 1 Frot 1 - Slo	
22 Owner 107 Vertical Supports Type 23 Orig Project Number 109 Truck ADT 23E Subaccount Number 109 Truck ADT 23E Project Indicator 110 Designated National Network 23E Project Indicator 111 Future ADT 26 Functional Class 114 Future ADT 27 Year Built 115 Year of Future ADT 28A Lanes on Structure 06 28B Lanes In Front 00 29 Average Daily Traffic 125AB Type of Wall Rail on Top 30 Year of ADT 133 Special Insp. Equipment 31 Inventory Route Median 2 - Closed Median (no barrier) 36H Rail Height. On Top NNNN 36H Rail Height. On Top N" 37 Historical Significance 14 Sub In Dist Fr Route, Carried 42 Type of Service, On J - Slope - Talus In Front U - Other 43 Wall Face Material 7 - Stone/Masini Type of Design/Construction 25 - Soil Nail 47 Tot Horz Clearance, Carried 035' 47A Tot Horz Clearance, In Front 005' 47A Tot Horz Clearance, In Front 005' 47A Tot Horz Clearance, In Front 000'	
23 Orig Project Number 23E Subaccount Number 23E Project Indicator 23E Project Indicator 23E Functional Class 26 Functional Class 27 Year Built 28A Lanes on Structure 28B Lanes on Structure 29 Average Daily Traffic 30 Year of ADT 30 Year of ADT 31 Inventory Route Median 32 - Closed Median (no barrier) 36AD Traffic Safety Features on Top 36H Rail Height. On Top 36H Rail Height of Rail In Front 36M Height of Rail In Front 36M Height of Rail In Front 37 Historical Significance 42 Type of Service, On In Front U - Other 43 Wall Face Material 7 - Yot or Seign/Construction 25 - Soil Naii 447 Tot Horz Clearance, Carried 47A Tot Horz Clearance, In Front 47A Tot Horz Clearance, In Front 47A To	
23E Subaccount Number 23E Project Indicator 26 Functional Class 27 Year Built 28A Lanes on Structure 29 Average Daily Traffic 30 Year of ADT 31 Inventory Route Median 2 - Closed Median (no barrier) 36L Traffic Safety Features on Top 36H Rail Height. On Top 36H Rail Height of Rail In Front 36M Height of Rail In Front 37 Historical Significance 42 Type of Service, On 1 J - Slope - Talus 1 Type of Design/Construction 43 Wall Face Material 7 - Stone/Masony Type of Design/Construction 47 Tot Horz Clearance, Carried 47A Tot Horz Clearance, In Front 47A Tot Horz Clearance, In Front	
23EE Project Indicator 113 Scour Critical Walls 26 Functional Class 114 Future ADT 27 Year Built 115 Year of Future ADT 28A Lanes on Structure 06 28B Lanes on Structure 06 29 Average Daily Traffic 133 Special Insp. Equipment 30 Year of ADT 133 Special Insp. Equipment 31 Inventory Route Median 2 - Closed Median (no barrier) 36AD Traffic Safety Features on Top 36H Rail Height. On Top 36H Rail Height of Rail In Front 37 Historical Significance 42 Type of Service, On In Front U - Other 43 Wall Face Material 7 - Stone/Masonry 144 Speed Limit, Rte Carried 47 Tot Horz Clearance, Carried 035' 47A Tot Horz Clearance, In Front 000'	
26 Functional Class 114 Future ADT 27 Year Built 115 Year of Future ADT 28A Lanes on Structure 06 28B Lanes In Front 00 29 Average Daily Traffic 125AB 30 Year of ADT 133 33 Inventory Route Median 2 - Closed Median (no barrier) 36AD Traffic Safety Features on Top NNNN 36H Rail Height. On Top N" 36H Rail Height of Rail In Front NNNN 36M Height of Rail In Front N" 37 Historical Significance N" 42 Type of Service, On J - Slope - Talus In Front U - Other 144 43 Wall Face Material 7 - Stone/Masonry Type of Design/Construction 25 - Soil Nail 146 47 Tot Horz Clearance, Carried 035' 47A Tot Horz Clearance, In Front 000' 47A Tot Horz Clearance, In Front 000'	
27 Year Built115 Year of Future ADT28A Lanes on Structure0628B Lanes In Front0029 Average Daily Traffic125CD Type of Wall Rail on Top30 Year of ADT133 Special Insp. Equipment31 Inventory Route Median2 - Closed Median (no barrier)36AD Traffic Safety Features on TopNNNN36H Rail Height. On TopN"36IL Traffic Safety Features in FrontNNNN36M Height of Rail In FrontN"36M Height of Rail In FrontN"37 Historical SignificanceN42 Type of Service, OnJ - Slope - TalusIn FrontU - Other43 Wall Face Material7 - Stone/MasonryType of Design/Construction25 - Soil Nail47 Tot Horz Clearance, Carried035'47A Tot Horz Clearance, In Front000'	
28ALanes on Structure06125ABType of Wall Rail on Top28BLanes In Front0029Average Daily Traffic30Year of ADT31Inventory Route Median2 - Closed Median (no barrier)36ADTraffic Safety Features on Top36HRail Height. On Top36HRail Height of Rail In Front36MHeight of Rail In Front36MHeight of Rail In Front37Historical Significance42Type of Service, OnIn FrontU - Other43Wall Face Material7Type of Design/Construction47Tot Horz Clearance, Carried47ATot Horz Clearance, In Front47ATot Horz Clearance, In Front47A <td< td=""><td></td></td<>	
28BLanes In Front0029Average Daily Traffic30Year of ADT31Inventory Route Median2 - Closed Median (no barrier)36ADTraffic Safety Features on Top36HRail Height. On Top36HRail Height On Top36HRail Height of Rail In Front36HHeight of Rail In Front36HRail Height of Rail In Front36HSefety Features in Front36HSefety Features in Front36HHeight of Rail In Front37Historical Significance42Type of Service, OnIn FrontU - Other43Wall Face Material7 - Stone/MasonryType of Design/Construction47Tot Horz Clearance, Carried47ATot Horz Clearance, In Front47ATot Horz Clearance, In Front	
29Average Daily Traffic30Year of ADT33Inventory Route Median2 - Closed Median (no barrier)36ADTraffic Safety Features on TopNNNN36HRail Height. On TopN"36HRail Height of Rail In FrontNNNN36MHeight of Rail In FrontN"37Historical SignificanceN"42Type of Service, OnJ - Slope - TalusIn FrontU - Other43Wall Face Material7 - Stone/MasonryType of Design/Construction25 - Soil Nail47Tot Horz Clearance, In Front000'47ATot Horz Clearance, In Front000'	<u> </u>
30Year of ADT33Inventory Route Median2 - Closed Median (no barrier)36ADTraffic Safety Features on TopNNNN36HRail Height. On TopN"36ILTraffic Safety Features in FrontNNNN36MHeight of Rail In FrontN"37Historical SignificanceV42Type of Service, OnJ - Slope - TalusIn FrontU - Other43Wall Face Material7 - Stone/MasonryType of Design/Construction25 - Soil Nail47Tot Horz Clearance, Carried035'47ATot Horz Clearance, In Front000'	
33Inventory Route Median2 - Closed Median (no barrier)36ADTraffic Safety Features on TopNNNN36HRail Height. On TopNNNN36ILTraffic Safety Features in FrontNNNN36MHeight of Rail In FrontNNNN36MHeight of Rail In FrontN"37Historical SignificanceN42Type of Service, OnJ - Slope - TalusIn FrontU - Other43Wall Face Material7 - Stone/MasonryType of Design/Construction25 - Soil Nail47Tot Horz Clearance, Carried035'47ATot Horz Clearance, In Front000'	
36ADTraffic Safety Features on TopNNNNMax Dist Fr Route, Carried36HRail Height. On TopN"Avg Dist Fr Route, Carried36ILTraffic Safety Features in FrontNNNN143BMin Dist Fr Route, In Front36MHeight of Rail In FrontN"Max Dist Fr Route, In Front37Historical SignificanceNMax Dist Fr Route, In Front42Type of Service, OnJ - Slope - Talus144AIn FrontU - Other144BSpeed Limit, Rte Carried43Wall Face Material7 - Stone/Masonry145Type of Design/Construction25 - Soil Nail147Vertical Batter47Tot Horz Clearance, Carried035'147Vertical Batter47ATot Horz Clearance, In Front000'148Slope Angle Carried & In Front	0180
36HRail Height. On TopN"Avg Dist Fr Route, Carried36ILTraffic Safety Features in FrontNNNN143BMin Dist Fr Route, In Front36MHeight of Rail In FrontN"Max Dist Fr Route, In Front37Historical SignificanceN"Avg Dist Fr Route, In Front42Type of Service, OnJ - Slope - Talus144AIn FrontU - Other144BSpeed Limit, Rte Carried43Wall Face Material7 - Stone/Masonry145Wall SystemType of Design/Construction25 - Soil Nail146Associated Bridge #47Tot Horz Clearance, Carried035'147Vertical Batter47ATot Horz Clearance, In Front000'148Slope Angle Carried & In Front	0180'
36IL Traffic Safety Features in Front NNNN 36M Height of Rail In Front N" 36M Height of Rail In Front N" 37 Historical Significance Avg Dist Fr Route, In Front 42 Type of Service, On J - Slope - Talus In Front U - Other 43 Wall Face Material 7 - Stone/Masonry Type of Design/Construction 25 - Soil Nail 47 Tot Horz Clearance, Carried 035' 47A Tot Horz Clearance, In Front 000'	0400' 0370'
36M Height of Rail In Front N" Max Dist Fr Route, In Front 37 Historical Significance Avg Dist Fr Route, In Front Avg Dist Fr Route, In Front 42 Type of Service, On J - Slope - Talus 144A Speed Limit, Rte Carried 1n Front U - Other 144B Speed Limit, Rte in Front 43 Wall Face Material 7 - Stone/Masonry Type of Design/Construction 25 - Soil Nail 47 Tot Horz Clearance, Carried 035' 47A Tot Horz Clearance, In Front 000'	
37 Historical Significance Avg Dist Fr Route, In Front 42 Type of Service, On J - Slope - Talus In Front U - Other 43 Wall Face Material 7 - Stone/Masonry Type of Design/Construction 25 - Soil Nail 47 Tot Horz Clearance, Carried 47A Tot Horz Clearance, In Front	00NA'
42 Type of Service, On J - Slope - Talus 144A Speed Limit, Rte Carried In Front U - Other 144B Speed Limit, Rte in Front 43 Wall Face Material 7 - Stone/Masonry 145 Wall System Type of Design/Construction 25 - Soil Nail 146 Associated Bridge # 47 Tot Horz Clearance, Carried 035' 147 Vertical Batter 47A Tot Horz Clearance, In Front 000' 148 Slope Angle Carried & In Front	00NA'
In FrontU - Other144B Speed Limit, Rte in Front43 Wall Face Material7 - Stone/Masonry145 Wall SystemType of Design/Construction25 - Soil Nail146 Associated Bridge #47 Tot Horz Clearance, Carried035'147 Vertical Batter47A Tot Horz Clearance, In Front000'148 Slope Angle Carried & In Front	00NA'
43 Wall Face Material 7 - Stone/Masonry 145 Wall System Type of Design/Construction 25 - Soil Nail 146 Associated Bridge # 47 Tot Horz Clearance, Carried 035' 147 Vertical Batter 47A Tot Horz Clearance, In Front 000' 148 Slope Angle Carried & In Front	45
Type of Design/Construction 25 - Soil Nail 146 Associated Bridge # 47 Tot Horz Clearance, Carried 035' 147 Vertical Batter 47A Tot Horz Clearance, In Front 000' 148 Slope Angle Carried & In Front	00
47 Tot Horz Clearance, Carried 035' 47A Tot Horz Clearance, In Front 000' 148 Slope Angle Carried & In Front	
47A Tot Horz Clearance, In Front 000' 148 Slope Angle Carried & In Front	
	90
49 Structure Lengtri 1723.00000 149 Protective Coating Type	11

Wall Inspection Report

Structure ID#: Southlands Mall - Bottom Wall

Inspection Date: 2022-07-07

Structure Notes:

Collins Engineers conducted an inspection to establish a baseline for future inspections following the failure and subsequent repair of three locations in the bottom retaining wall of a set of three walls that carry E. Smoky Hill Rd. between S. Main St. and S. Aurora Pkwy. at Southlands Mall.

Prior to Collins' inspection the three failed areas at Sta. 5+55, Sta. 7+28, and Sta. 14+55 had been repaired with split-face concrete masonry unit blocks to match the remainder of the wall. Isolated areas of the masonry capstone blocks had been replaced in these areas. The repaired areas were in good condition during Collins' 2022 inspection.

Inspection Notes:

The structure was inventoried from west to east. Notes in this report are referenced with stations beginning at the west end of the structure to assist future inspectors in assessing noted defects.

<u>Collins' recommends conducting a follow-up inspection in 12 months to monitor the condition of the repaired area, as well as the isolated area of bulging.</u>

Special Notes:

It appeared that most of the fill displacement and drainage issues were due to excessive seasonal run-off from the carried roadway above. Although the repairs were made to the wall facing and extra drainage relief was installed, it appeared that continued excessive run-off was still occurring due to the displaced stone and clogged weep hole.

Wall Inspection Report

Structure ID#: Southlands Mall - Bottom Wall

Inspection Date: 2022-07-07

BrM and Element Data Collection

Element # Defect	Element Description	Total Qty	Units	Env. Factor	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
9705	Masonry Wall	15507	SF	1	14131	1375	1	0
1080	Delamination/Spall/ Patched Area			1	0	0	1	0
1640	Masonry Displacement			1	0	10	0	0
1910	Bulging			1	0	540	0	0
1960	Vegetation Growth			1	0	50	0	0
2310	Leakage			1	0	775	0	0
9750	Retained Material	1723	LF	1	1723	0	0	0
9763	Other Joint	1	EA	1	1	0	0	0
9770	Weep Holes/Slots	14	EA	1	14	0	0	0
9773	Other Drain	2	EA	1	1	1	0	0
1970	Blockage			1	0	1	0	0
9780	Metal Wall Railing	330	LF	1	330	0	0	0

Element	Description	Element Notes
9705	Masonry Wall	The wall facing was comprised of split-face concrete masonry unit (CMU) blocks that measured 8 in. high by 18 in. long. The wall facing was in good condition. The wall facing included a masonry capstone block for full length at the top of the wall. There were isolated replacement capstones, totaling approximately 35 LF, between Sta. 14+00 and Sta. 16+30 and at Sta. 5+70. The shotcrete wall was exposed through the gravel ballast at the top of the wall facing at isolated locations near the east end of the wall. The exposed shotcrete was secure and in good condition.
		 The (3) previously reported areas of failure (area) in the wall facing had been repaired to match the remainder of the wall: 1. The area located at Sta. 5+55 (previously referenced as 23962) was in good condition and a 4.5 in. diameter weep hole had been installed 2 ft. above grade. 2. The area located at Sta. 7+28 (previously referenced as 23972) was in good condition. 3. The area located at Sta. 14+55 (previously referenced as 24192) was in good condition and a 4.5 in. diameter weep hole had been installed at grade at Sta. 14+65.
		The wall facing typically exhibited intermittent areas of mortar residue on the edges of blocks in/around the previously reported areas of failure.
		(CS3) - Split/Spall (Masonry): The wall facing exhibited a spall measuring 4 in. long by 5 in. high by 1.5 in. penetration in the second from bottom course at Sta. 13+14.
		(CS2) - Masonry Displacement: The top of the wall exhibited isolated areas of displaced capstone blocks, predominantly at the north segment of the wall at the west end.
		(CS2) - Vegetation Growth: There was minor vegetation growth at the west end of the wall.
		(CS2) - Leakage: The wall facing exhibited intermittent moisture staining consisting of discoloration emanating from between courses at approximately 5% of the wall facing area. There was an isolated area of saturated ground at the toe of the wall and moisture stained blocks for 6 ft. along the bottom course at Sta. 12+57.
		(CS2) - Bulging: The top of the wall was bowed to the north up to 1 in. out of plane away from the fill material from the top of the wall to 2 ft. below the top between Sta. 4+90 and Sta. 5+50. This area was immediately west of the previously reported area of failure at Sta. 5 +55.
9750	Retained Material	The retained fill was in good condition with no observed areas of backfill loss through the wall facing. There were isolated areas of gravel ballast loss at the top of the wall that had exposed the top course of the masonry facing beneath the capstone. There were isolated areas of newer/replaced gravel ballast at the top of the wall near Sta. 14+55.
9763	Other Joint	There was (1) joint/discontinuity in the masonry wall facing at Sta. 4+11. There were no observed defects at the joint.
9770	Weep Holes/Slots	The (14) weep holes consisted of 4.5 in. diameter corrugated plastic and were in good condition throughout.
9773	Other Drain	This element serves to quantify the (2) drains that were installed within the upper 3 ft. of the wall facing at the west end.
		(CS2) - Blockage: The drain that the weep in the wall feeds into at Sta. 1 +86 was partially obstructed with debris.
9780	Metal Wall Railing	This element represents the two segments of the wrought iron pedestrian railing at either side of the bend in the northwest corner of the wall. The railing measured 38 in. from grade and was in good condition.

Wall Inspection Report

Maintenance/Repair Recommendations

Structure ID#: Southlands Mall - Bottom Wall

Inspection Date: 2022-07-07


Activity No : Description:	377.03 Install weep holes (for walls with no prior drainage)	Priority: Medium
Detail of Work		wall and area of moisture stained bottom course at Sta. 12+57
Maint Qty :	1 EA	Maint Cost: \$
		Target Year: 2023
Activity No : Description: Detail of Work	351.00 Wall/Structural Visual Inspection/Monitoring Monitor wall facing for drainage issues, concentrated a 7+28, Sta. 14+55. Monitor area of bulging near top of	Priority: Medium at previous areas of failure at the following stations: Sta. 5+55, Sta

Priority Level 1 - High (Orange)	Repair within the time specified by the inspector or at most within 30 days
Priority Level 2 - Medium (Yellow)	Repair within 90 days
Priority Level 3 - Low (Green)	Repair within one year or as funding allows

Wall Inspection Report

Structure ID#: Southlands Mall - Bottom Wall

Inspection Date: 2022-07-07




Overview of Wall on E. Smoky Hill Road

Start of Wall: 39.59811,-104.70618

End of Wall: 39.60048,-104.71057

PHOTO LOG

General Overview	Photo 1	Elevation looking southeast
---------------------	---------	-----------------------------



Elevation, Looking Southeast



Roadway Carried, Looking West



Roadway Carried, Looking Southeast



View of Repaired Area in Wall Facing at Sta. 5+55



View of Repaired Area in Wall Facing at Sta. 7+28




View of Spall in Wall Facing at Sta. 13+14



Moisture Staining at Wall Facing and Area of Saturated Ground at Toe of Wall at Sta. 12+57



View of Repaired Area in Wall Facing at Sta. 14+55



Intermittent Areas of Mortar Residue on Edges of Blocks East of Sta. 14+55



Typical Replaced Masonry Capstone at Top of Wall



Areas of Newer/Replaced Gravel Ballast at Top of Wall at Sta. 14+55



Typical Exposed Top Course of Masonry Block at Top of Wall



Typical Exposed Shotcrete Wall Behind Top of Masonry Wall Facing



View of Bowed Area of Wall Facing at Sta. 4+90



Partially Obstructed Drain at Weep Hole at Top of Wall at Sta. 1+86

Wall Inspection Report

Structure ID#: Southland	s Mall - Middle Wall	Insj	pection Date: 2022-07-07
Owner:		Year Built:	
Maintained By:	Private	Region/Section:	
Main Structure Type:	25 - Soil Nail	Start of Wall MP:	
Location:	E. Smoky Hill b/wn Main & Aurora	Route:	
Service Type-Carried:	J - Slope - Talus	Features Carried:	E. Smoky Hill Rd.
Service Type-In Front:	U - Other	Features In Front:	Commercial
Inspection Frequency:	48 months	Wall Risk:	
		Essential I	Repair Finding

Inspection Scopes: X NBI Element Underwater Other Inspection Type: 1 - Regular NBI



Elevation looking southeast

OVERALL RATINGS	Inspection Team	Ag	gency
Main Structure: 7	Danny Debes - Team Leade	er Co	ollins Engineers
Foundation: <u>N</u> Channel & Channel Protection: N	Jack Summers - Team Men	nber Co	ollins Engineers
		Ins	spection Resources
Project [.] S	outhland Mall- Ret. Wall INSP	Crew Hou	urs0.5
Project Number:		Flagger Hou	urs <u>0.0</u>
	050 F	Helper Hou	urs <u>0.0</u>
Temperature:		Snooper Hou	urs <u>0.0</u>
Weather Conditions:	Sunny	Special Crew Hou	urs <u>0.0</u>
		Special Equipment Hou	urs <u>0.0</u>
Access Issues:	Animals 3rd Party Fen	icing 🗌 Other:	

Wall Inspection Report

Structure ID#: Southlands Mall - Middle Wall

Inspection Date: 2022-07-07

2E/M 3 4	State Name Region/Maint Section		088 - Colorado	50A	Curb or Sidewalk, Carried(L)	1	
3 4	Region/Maint Section						00'
3 4				50B	Curb or Sidewalk, Carried(R)	1	00'
4	County Code		005 - Arapahoe		Curb or Sidewalk, In Front(L)		000'
	Place Code	0	4000 - AURORA		Curb or Sidewalk, In Front(R))00'
. : A	Inventory Rte (On/In Front)		ntory Rte Carried		Width Curb-to-Curb, Carried		350'
	Inventory Rte (Signing)				Width Curb-to-Curb, In Front		000'
	Inventory Rte (L.O.S.)				Average Wall Height	8.000	
	Inventory Rte (Rte Num)				Maximum Wall Height)10'
	Inventory Rte (Dir Suffix)				Minimum Wall Height)02'
		F	. Smoky Hill Rd.		Main Structure	7 - Good Condi	-
7			Commercial		Foundation	N - Not Applica	
8	Structure ID Number		Commercial		Channel & Channel Protection	N - Not Applica	
-	Structure Number				Water Adequacy	N - Not Applica	
	Location	E. Smoky Hill b/w	n Main & Aurora		Adjacent Roadway Alignment	N - Not Applica	
-	Reference Point		All Maill & Autora		Inspection Date	2022-07	_
	Base Hwy Network				-		-07 8 m
	LRS Inventory & Subroute #				Frequency	40	5 111
	,	20255022	20 50054		Crit Feat Insp - Underwater		
	Latitude Start-of-Wall	39355822 39355358	39.59951		Crit Feat Insp - Special		
	Latitude End-of-Wall	39355358	39.59822		Underwater Inspection Date		
	Start of Wall Elevation				Special Inspection Date		
	Longitude Start-of-Wall	104423474	-104.70965		Border Wall State Code		
	Longitude End-of-Wall	104422155	-104.70599		Percent Responsibility		
	End of Wall Elevation		'		Border Wall Structue #		
	Range				STRAHNET Hwy Designation		
	Township			_	Direction of Traffic		
	Section				Temp Structure Designation		
	Bypass Detour Length				Highway System		
-	Toll				Federal Lands Highway		
21	Maint. Responsibility				Year Reconstructed		
	Owner				Vertical Supports Type		
23	Orig Project Number				Truck ADT		
23E	Subaccount Number			110	Designated National Network		
23EE	Project Indicator			113	Scour Critical Walls		
26	Functional Class			114	Future ADT		
27	Year Built			115	Year of Future ADT		
28A	Lanes on Structure		06	125AB	Type of Wall Rail on Top		
28B	Lanes In Front		00	125CD	Type of Wall Rail in Front		
29	Average Daily Traffic			133	Special Insp. Equipment		
30	Year of ADT			136	Mileage Log Section Letter		
33	Inventory Route Median			143A	Min Dist Fr Route, Carried	01	80'
	Traffic Safety Features on Top		NNNN		Max Dist Fr Route, Carried	04	00'
36H	Rail Height. On Top		N"		Avg Dist Fr Route, Carried	03	370'
	Traffic Safety Features in Front		NNNN	143B	Min Dist Fr Route, In Front	00	NA'
36M	Height of Rail In Front		N"		Max Dist Fr Route, In Front	00	NA'
37	Historical Significance				Avg Dist Fr Route, In Front	00	NA'
42	Type of Service, On		J - Slope - Talus	144A	Speed Limit, Rte Carried		45
	In Front		U - Other		Speed Limit, Rte in Front		00
43	Wall Face Material	7	- Stone/Masonry		Wall System		
-	Type of Design/Construction		25 - Soil Nail		Associated Bridge #		
47	Tot Horz Clearance, Carried		035'		Vertical Batter		90
	Tot Horz Clearance, In Front		000'		Slope Angle Carried & In Front		11
	Structure Length		1230.00000'		Protective Coating Type		
10			1200.00000	110	recente cealing type		

Wall Inspection Report

Structure ID#: Southlands Mall - Middle Wall

Inspection Date: 2022-07-07

Structure Notes:

The structure was inventoried from west to east. Notes in this report are referenced with stations beginning at the west

end of the structure.

Inspection Notes:

Collins Engineers conducted an inspection of the wall to establish a baseline for future inspections following the failure

and subsequent repair of the bottom wall of the three retaining walls carrying E. Smoky Hill Rd. between S. Main St. and

S. Aurora Pkwy. at Southlands Mall.

Special Notes:

It appeared that most of the fill displacement and drainage issues were due to excessive seasonal run-off from the carried roadway above. Although the repairs were made to the wall facing and extra drainage relief was installed, it appeared that continued excessive run-off was still occurring due to the displaced stone and clogged weep hole.

Wall Inspection Report

Structure ID#: Southlands Mall - Middle Wall

Inspection Date: 2022-07-07

BrM and Element Data Collection

Element # Defect	Element Description	Total Qty	Units	Env. Factor	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
9705	Masonry Wall	9840	SF	1	9839	1	0	0
1620	Split/Spall (Masonry)			1	0	1	0	0
9750	Retained Material	1230	LF	1	1222	4	4	0
5010	Backfill Loss			1	0	2	4	0
5030	Erosion			1	0	2	0	0
9763	Other Joint	1	EA	1	1	0	0	0
9770	Weep Holes/Slots	2	EA	1	0	0	1	1
1970	Blockage			1	0	0	1	0
7000	Damage			1	0	0	0	1
9773	Other Drain	1	EA	1	1	0	0	0

Element	Description	Element Notes
9705	Masonry Wall	The wall facing was comprised of split-face concrete masonry unit (CMU) blocks that measured 8 in. high by 18 in. long. The wall facing was in good condition. The wall facing included a masonry capstone block for full length at the top of the wall.
		The shotcrete wall was intermittently exposed through the gravel ballast at the top of the wall facing for 100 ft. at the east end. The exposed shotcrete was in good condition and exhibited exposed reinforcing steel that was in good condition. There was an area of debris/gravel ballast build up at the base of the wall for 40 ft. beginning at Sta. 1+70.
		(CS2) - Split/Spall (Masonry): The wall facing exhibited (2) full block height splits up to 1/8 in. wide in a block at Sta. 3+45. The block was secure and had not shifted.
9750	Retained Material	The retained fill was in fair condition. There were isolated areas of gravel ballast loss at the top of the wall that had exposed the top course of the masonry facing beneath the capstone.
		(CS3) - Backfill Loss: There was an isolated area of backfill loss at Sta. 11+30 measuring 4 ft. long at the improperly installed weep hole. The plastic pipe terminated behind the masonry facing allowing the backfill to spill out of the weep hole cutout.
		(CS2) - Backfill Loss: There was an area of minor backfill loss from between masonry blocks at Sta. 3+26.
		(CS2) - Erosion: There was an area of undermining below the bottom course measuring 15 in. long by 4 in. vertical exposure by 13 in. penetration at Sta. 11+79.
9763	Other Joint	There was (1) joint/discontinuity in the masonry wall facing at Sta. 2+62. There were no observed defects at the joint.
9770	Weep Holes/Slots	There were (2) weep holes consisting of 4.5 in. diameter corrugate plastic.
		(CS4) - Damage: The weep hole at Sta. 11+30 was improperly installed. The plastic pipe did not extend through the masonry facing and terminated within the wall behind the block.
		(CS3) - Blockage: The weep hole at Sta. 7+51 was partially buried and obstructed by gravel ballast at the toe of the wall.
9773	Other Drain	There was a corrugated plastic drainage pipe measuring 4.5 in. in diameter installed vertically through a capstone at Sta. 2+94. The drain appeared to be in good condition.

Wall Inspection Report

Maintenance/Repair Recommendations

Structure ID#: Southlands Mall - Middle Wall

Inspection Date: 2022-07-07

Activity No : Description:	377.01 Repair/Replace weep holes	Priority	: Medium
Detail of Work	Extend pipe to terminate beyond wall facing at weep		
	hole at Sta. 11+30.	Maint Cost:	\$
Maint Qty :	1 EA	Target Year:	2023
		Target Tear.	2020
Activity No :	377.01		: Medium
Description:	377.01 Repair/Replace weep holes	Priority	
Description:	377.01	Priority	
Activity No : Description: Detail of Work Maint Qty :	377.01 Repair/Replace weep holes	Priority	: Medium

Priority Definitions

Priority Level 1 - High (Orange)	Repair within the time specified by the inspector or at most within 30 days
Priority Level 2 - Medium (Yellow)	Repair within 90 days
Priority Level 3 - Low (Green)	Repair within one year or as funding allows

Wall Inspection Report



Overview of Wall on E. Smoky Hill Road

Start of Wall: 39.59951,-104.70965

Ma

data ©2022 Ima

End of Wall: 39.59822,-104.70599

Survey USDA/FPAC/GF

PHOTO LOG

General Overview	Photo 1	Elevation looking southeast
Inventory Roadway	Photo 2	Roadway carried looking west
Inventory Roadway	Photo 3	Roadway carried looking southeast
Defect	Photo 4	Splits in CMU Block at Sta. 3+45
Defect	Photo 5	Backfill Loss Through Improperly Installed Weep Hole at Sta. 11+30
Defect	Photo 6	View of Improperly Installed Weep Hole at Sta. 11+30
Defect	Photo 7	Area of Undermining at Sta. 11+79
Defect	Photo 8	Obstructed Weep Hole at Sta. 7+51
General	Photo 9	Typical Exposed Shotcrete Wall with Exposed Reinforcing Steel at East End o Wall
General	Photo 10	Vertical Drain through Capstone at Sta. 2+94
General	Photo 11	Typical Mortar Residue on Wall Facing

Southland Walls Inspection - Middle Wall - 07/07/2022



Elevation, Looking Southeast



Roadway Carried, Looking West



Roadway Carried, Looking Southeast



Splits in CMU Block at Sta. 3+45

Southland Walls Inspection - Middle Wall - 07/07/2022



Backfill Loss Through Improperly Installed Weep Hole at Sta. 11+30



Area of Undermining at Sta. 11+79



View of Improperly Installed Weep Hole at Sta. 11+30



Obstructed Weep Hole at Sta. 7+51

Southland Walls Inspection - Middle Wall - 07/07/2022



Typical Exposed Shotcrete Wall with Exposed Reinforcing Steel at East End of Wall



Typical Mortar Residue on Wall Facing



Vertical Drain through Capstone at Sta. 2+94

Wall Inspection Report

Inspection Date: 2022-07-07

Owner:	Private
Maintained By:	Private
Main Structure Type:	25 - Soil Nail
Location:	E. Smoky Hill b/wn Main & Aurora
Service Type-Carried:	J - Slope - Talus
Service Type-In Front:	J - Slope - Talus
Inspection Frequency:	48 months

Year Built: Region/Section: Start of Wall MP:	
Route:	
Features Carried:	E. Smoky Hill Rd.
Features In Front:	Commercial
Wall Risk:	
Essentia	al Repair Finding

Inspection Scopes: NBI X Element Underwater Other Inspection Type: 1 - Regular NBI



Elevation looking southeast

OVERALL RATINGS	Inspection Team	Agency	,
Main Structure: 7	Danny Debes - Team Leade	er Collins	Engineers
Foundation: <u>N</u> Channel & Channel Protection: <u>N</u>	Jack Summers - Team Men	nber Collins	Engineers
		Inspect	ion Resources
Project: <u>Sc</u>	outhland Mall- Ret. Wall INSP	Crew Hours	0.5
Project Number:		Flagger Hours	0.0
	050 F	Helper Hours	0.0
Temperature:		Snooper Hours	0.0
Weather Conditions:	Sunny	Special Crew Hours	0.0
		Special Equipment Hours	0.0
		cia a Doth car	
Rail Road MOHT	Animals 3rd Party Fen	cing Other:	

Wall Inspection Report

Structure ID#: Southlands Mall - Top Wall

Inspection Date: 2022-07-07

ame Maint Section Code ode y Rte (On/In Front) y Rte (Signing) y Rte (L.O.S.) y Rte (Rte Num) y Rte (Dir Suffix) s Carried s In Front e ID Number e Number n ce Point vy Network entory & Subroute # Start-of-Wall End-of-Wall Wall Elevation de End-of-Wall Vall Elevation		088 - Colorado 005 - Arapahoe 04000 - AURORA /entory Rte Carried E. Smoky Hill Rd. Commercial //wn Main & Aurora 39.59912 39.59803 -104.70885 -104.70885	50B 50C 50D 511 51A 52 53 54 58 60 61 71 72 90 91 92B 92C 93B 93C 98A	Curb or Sidewalk, Carried(L) Curb or Sidewalk, Carried(R) Curb or Sidewalk, In Front(L) Curb or Sidewalk, In Front(R) Width Curb-to-Curb, Carried Width Curb-to-Curb, In Front Average Wall Height Mainmum Wall Height Main Structure Foundation Channel & Channel Protection Water Adequacy Adjacent Roadway Alignment Inspection Date Frequency Crit Feat Insp - Underwater Crit Feat Insp - Special Underwater Inspection Date Special Inspection Date		100' 100' 000' 000' 0000' 8.00000' 8.00000' 0009' 0001' 7 - Good Condition N - Not Applicable N - Not Applicable 2022-07-07 48 m
Code ode y Rte (On/In Front) y Rte (Signing) y Rte (L.O.S.) y Rte (Rte Num) y Rte (Dir Suffix) s Carried s In Front e ID Number e Number e Number of ce Point vy Network entory & Subroute # Start-of-Wall End-of-Wall Wall Elevation de End-of-Wall Vall Elevation	E. Smoky Hill b 39355683 39355290 104423185	04000 - AURORA /entory Rte Carried E. Smoky Hill Rd. Commercial //wn Main & Aurora 39.59912 39.59803 -104.70885	50C 50D 51 51A 52 53 54 58 60 61 71 72 90 91 92B 92C 93B 93C 98A	Curb or Sidewalk, In Front(L) Curb or Sidewalk, In Front(R) Width Curb-to-Curb, Carried Width Curb-to-Curb, In Front Average Wall Height Maximum Wall Height Main Structure Foundation Channel & Channel Protection Water Adequacy Adjacent Roadway Alignment Inspection Date Frequency Crit Feat Insp - Underwater Crit Feat Insp - Special Underwater Inspection Date		000' 000' 0350' 0000' 8.00000' 0009' 0001' 7 - Good Condition N - Not Applicable N - Not Applicable
ode y Rte (On/In Front) y Rte (Signing) y Rte (L.O.S.) y Rte (Rte Num) y Rte (Dir Suffix) s Carried s In Front e ID Number e Number h ce Point vy Network entory & Subroute # Start-of-Wall End-of-Wall Wall Elevation de End-of-Wall Vall Elevation	E. Smoky Hill b 39355683 39355290 104423185	04000 - AURORA /entory Rte Carried E. Smoky Hill Rd. Commercial //wn Main & Aurora 39.59912 39.59803 -104.70885	50D 51 51A 52 53 54 58 60 61 71 72 90 91 92B 92C 93B 93C 98A	Curb or Sidewalk, In Front(R) Width Curb-to-Curb, Carried Width Curb-to-Curb, In Front Average Wall Height Maximum Wall Height Minimum Wall Height Main Structure Foundation Channel & Channel Protection Water Adequacy Adjacent Roadway Alignment Inspection Date Frequency Crit Feat Insp - Underwater Crit Feat Insp - Special Underwater Inspection Date		000' 0350' 0000' 8.00000' 0009' 0001' 7 - Good Condition N - Not Applicable N - Not Applicable N - Not Applicable N - Not Applicable 2022-07-07
y Rte (On/In Front) y Rte (Signing) y Rte (L.O.S.) y Rte (Rte Num) y Rte (Dir Suffix) s Carried s In Front e ID Number e Number e Number of ce Point vy Network entory & Subroute # Start-of-Wall End-of-Wall Wall Elevation de End-of-Wall Vall Elevation	E. Smoky Hill b 39355683 39355290 104423185	Ventory Rte Carried E. Smoky Hill Rd. Commercial V/wn Main & Aurora 39.59912 39.59803 ' -104.70885	51 51A 52 53 54 58 60 61 71 72 90 91 92B 92C 93B 93C 98A	Width Curb-to-Curb, Carried Width Curb-to-Curb, In Front Average Wall Height Maximum Wall Height Minimum Wall Height Main Structure Foundation Channel & Channel Protection Water Adequacy Adjacent Roadway Alignment Inspection Date Frequency Crit Feat Insp - Underwater Crit Feat Insp - Special Underwater Inspection Date		0350' 0000' 8.00000' 0009' 0001' 7 - Good Condition N - Not Applicable N - Not Applicable N - Not Applicable N - Not Applicable 2022-07-07
y Rte (Signing) y Rte (L.O.S.) y Rte (Rte Num) y Rte (Dir Suffix) s Carried s In Front e ID Number e Number e Number of Ce Point vy Network entory & Subroute # Start-of-Wall End-of-Wall Wall Elevation de End-of-Wall Vall Elevation	E. Smoky Hill b 39355683 39355290 104423185	E. Smoky Hill Rd. Commercial //wn Main & Aurora 39.59912 39.59803 -104.70885	51A 52 53 54 58 60 61 71 72 90 91 92B 92C 93B 92C 93B 93C 98A	Width Curb-to-Curb, In Front Average Wall Height Maximum Wall Height Minimum Wall Height Main Structure Foundation Channel & Channel Protection Water Adequacy Adjacent Roadway Alignment Inspection Date Frequency Crit Feat Insp - Underwater Crit Feat Insp - Special Underwater Inspection Date		0000' 8.00000' 0009' 0001' 7 - Good Condition N - Not Applicable N - Not Applicable N - Not Applicable N - Not Applicable 2022-07-07
y Rte (L.O.S.) y Rte (Rte Num) y Rte (Dir Suffix) s Carried s In Front e ID Number e Number n ce Point vy Network entory & Subroute # Start-of-Wall End-of-Wall Wall Elevation de End-of-Wall Vall Elevation	39355683 39355290 104423185	Commercial /wn Main & Aurora 39.59912 39.59803 -104.70885	52 53 54 58 60 61 71 72 90 91 92B 92C 93B 93C 93A	Average Wall Height Maximum Wall Height Minimum Wall Height Main Structure Foundation Channel & Channel Protection Water Adequacy Adjacent Roadway Alignment Inspection Date Frequency Crit Feat Insp - Underwater Crit Feat Insp - Special Underwater Inspection Date		8.00000' 0009' 0001' 7 - Good Condition N - Not Applicable N - Not Applicable N - Not Applicable N - Not Applicable 2022-07-07
y Rte (Rte Num) y Rte (Dir Suffix) s Carried s In Front e ID Number e Number e Number o ce Point vy Network entory & Subroute # Start-of-Wall End-of-Wall Wall Elevation de End-of-Wall Vall Elevation	39355683 39355290 104423185	Commercial /wn Main & Aurora 39.59912 39.59803 -104.70885	53 54 58 60 61 71 72 90 91 92B 92C 93B 93C 93A	Maximum Wall Height Minimum Wall Height Main Structure Foundation Channel & Channel Protection Water Adequacy Adjacent Roadway Alignment Inspection Date Frequency Crit Feat Insp - Underwater Crit Feat Insp - Special Underwater Inspection Date		0009' 0001' 7 - Good Condition N - Not Applicable N - Not Applicable N - Not Applicable N - Not Applicable 2022-07-07
y Rte (Dir Suffix) s Carried s In Front e ID Number e Number o ce Point vy Network entory & Subroute # Start-of-Wall End-of-Wall Wall Elevation de End-of-Wall Vall Elevation	39355683 39355290 104423185	Commercial /wn Main & Aurora 39.59912 39.59803 -104.70885	54 58 60 61 71 72 90 91 92B 92C 93B 93C 93A	Minimum Wall Height Main Structure Foundation Channel & Channel Protection Water Adequacy Adjacent Roadway Alignment Inspection Date Frequency Crit Feat Insp - Underwater Crit Feat Insp - Special Underwater Inspection Date		0001' 7 - Good Condition N - Not Applicable N - Not Applicable N - Not Applicable N - Not Applicable 2022-07-07
s Carried s In Front e ID Number e Number ce Point vy Network entory & Subroute # Start-of-Wall End-of-Wall Wall Elevation de End-of-Wall Vall Elevation	39355683 39355290 104423185	Commercial /wn Main & Aurora 39.59912 39.59803 -104.70885	58 60 61 71 72 90 91 92B 92C 93B 93C 93A	Main Structure Foundation Channel & Channel Protection Water Adequacy Adjacent Roadway Alignment Inspection Date Frequency Crit Feat Insp - Underwater Crit Feat Insp - Special Underwater Inspection Date		7 - Good Condition N - Not Applicable N - Not Applicable N - Not Applicable N - Not Applicable 2022-07-07
s In Front e ID Number e Number ce Point vy Network entory & Subroute # Start-of-Wall End-of-Wall Wall Elevation de Start-of-Wall de End-of-Wall Vall Elevation	39355683 39355290 104423185	Commercial /wn Main & Aurora 39.59912 39.59803 -104.70885	60 61 71 72 90 91 92B 92C 93B 93C 93A	Foundation Channel & Channel Protection Water Adequacy Adjacent Roadway Alignment Inspection Date Frequency Crit Feat Insp - Underwater Crit Feat Insp - Special Underwater Inspection Date		N - Not Applicable N - Not Applicable N - Not Applicable N - Not Applicable 2022-07-07
e ID Number e Number ce Point vy Network entory & Subroute # Start-of-Wall End-of-Wall Wall Elevation de End-of-Wall de End-of-Wall Vall Elevation	39355683 39355290 104423185	/wn Main & Aurora 39.59912 39.59803 -104.70885	61 71 72 90 91 92B 92C 93B 93C 93A	Channel & Channel Protection Water Adequacy Adjacent Roadway Alignment Inspection Date Frequency Crit Feat Insp - Underwater Crit Feat Insp - Special Underwater Inspection Date		N - Not Applicable N - Not Applicable N - Not Applicable 2022-07-07
e Number ce Point vy Network entory & Subroute # Start-of-Wall End-of-Wall Wall Elevation de Start-of-Wall de End-of-Wall Vall Elevation	39355683 39355290 104423185	39.59912 39.59803 -104.70885	71 72 90 91 92B 92C 93B 93C 98A	Water Adequacy Adjacent Roadway Alignment Inspection Date Frequency Crit Feat Insp - Underwater Crit Feat Insp - Special Underwater Inspection Date		N - Not Applicable N - Not Applicable 2022-07-07
n ce Point vy Network entory & Subroute # Start-of-Wall End-of-Wall Wall Elevation de Start-of-Wall de End-of-Wall Vall Elevation	39355683 39355290 104423185	39.59912 39.59803 -104.70885	72 90 91 92B 92C 93B 93C 98A	Adjacent Roadway Alignment Inspection Date Frequency Crit Feat Insp - Underwater Crit Feat Insp - Special Underwater Inspection Date		N - Not Applicable 2022-07-07
ce Point vy Network entory & Subroute # Start-of-Wall End-of-Wall Wall Elevation de Start-of-Wall de End-of-Wall Vall Elevation	39355683 39355290 104423185	39.59912 39.59803 -104.70885	90 91 92B 92C 93B 93C 93A	Inspection Date Frequency Crit Feat Insp - Underwater Crit Feat Insp - Special Underwater Inspection Date		2022-07-07
vy Network entory & Subroute # Start-of-Wall End-of-Wall Wall Elevation de Start-of-Wall de End-of-Wall Vall Elevation	39355683 39355290 104423185	39.59912 39.59803 -104.70885	90 91 92B 92C 93B 93C 93A	Inspection Date Frequency Crit Feat Insp - Underwater Crit Feat Insp - Special Underwater Inspection Date		2022-07-07
entory & Subroute # Start-of-Wall End-of-Wall Wall Elevation de Start-of-Wall de End-of-Wall Vall Elevation	39355290 104423185	39.59803 ' -104.70885	92B 92C 93B 93C 98A	Crit Feat Insp - Underwater Crit Feat Insp - Special Underwater Inspection Date		48 m
Start-of-Wall End-of-Wall Wall Elevation de Start-of-Wall de End-of-Wall Vall Elevation	39355290 104423185	39.59803 ' -104.70885	92C 93B 93C 98A	Crit Feat Insp - Special Underwater Inspection Date		
End-of-Wall Wall Elevation de Start-of-Wall de End-of-Wall Vall Elevation	39355290 104423185	39.59803 ' -104.70885	93B 93C 98A	Underwater Inspection Date		_
Wall Elevation de Start-of-Wall de End-of-Wall Vall Elevation	104423185	-104.70885	93B 93C 98A	Underwater Inspection Date		
de Start-of-Wall de End-of-Wall Vall Elevation			93C 98A			
de Start-of-Wall de End-of-Wall Vall Elevation			98A			
le End-of-Wall Vall Elevation				Border Wall State Code		
		1	98B	Percent Responsibility		
ip				Border Wall Structue #		
ip				STRAHNET Hwy Designation		
				Direction of Traffic		
•			_	Temp Structure Designation		
Detour Length				Highway System		
2 otodi 2ongin				Federal Lands Highway		
esponsibility				Year Reconstructed		
,				Vertical Supports Type		
ject Number				Truck ADT		
ount Number				Designated National Network		
ndicator				Scour Critical Walls		
nal Class				Future ADT		
ilt				Year of Future ADT		
n Structure		06		Type of Wall Rail on Top		
n Front		00		Type of Wall Rail in Front		
Daily Traffic				Special Insp. Equipment		
ADT				Mileage Log Section Letter		
y Route Median				Min Dist Fr Route, Carried		0180'
						0400'
				,		0400
						000NA'
•						00NA'
		<u>IN</u>				00NA 00NA'
		L Clana Talua		-		45
		-				
				•		00
-				-		
Corriad						11
,						11
z Clearance, In Front		323.00000	143	Trolective Coaling Type		
g ia al S C C C	afety Features on Top ht. On Top afety Features in Front Rail In Front Significance Service, On Material Design/Construction Clearance, Carried Clearance, In Front Length	ht. On Top afety Features in Front Rail In Front Significance Service, On Material Design/Construction Clearance, Carried Clearance, In Front	ht. On Top N" afety Features in Front NNNN Rail In Front N" Significance Service, On J - Slope - Talus Design/Construction 25 - Soil Nail Clearance, Carried 035' Clearance, In Front 000'	ht. On Top N" afety Features in Front NNNN Rail In Front N" Significance Service, On J - Slope - Talus 144A J - Slope - Talus 144B e Material 7 - Stone/Masonry 145 Design/Construction 25 - Soil Nail Clearance, Carried 035' 147 Clearance, In Front 000' 148	ht. On TopN"Avg Dist Fr Route, Carriedafety Features in FrontNNNN143BMin Dist Fr Route, In FrontRail In FrontN"N"Max Dist Fr Route, In FrontSignificanceJ - Slope - TalusAvg Dist Fr Route, In FrontService, OnJ - Slope - Talus144ASpeed Limit, Rte Carried144BJ - Slope - Talus144BSpeed Limit, Rte in Front144BDesign/Construction25 - Soil NailClearance, Carried035'Clearance, In Front000'148Slope Angle Carried & In Front	ht. On Top N" Avg Dist Fr Route, Carried afety Features in Front NNNN 143B Min Dist Fr Route, In Front Rail In Front N" Max Dist Fr Route, In Front Significance

Wall Inspection Report

Structure ID#: Southlands Mall - Top Wall

Inspection Date: 2022-07-07

Structure Notes:

Collins Engineers conducted an inspection of the wall to establish a baseline for future inspections following the failure

and subsequent repair of the bottom wall of the three retaining walls carrying E. Smoky Hill Rd. between S. Main St. and

S. Aurora Pkwy. at Southlands Mall.

Inspection Notes:

The structure was inventoried from west to east. Notes in this report are referenced with stations beginning at the west

end of the structure.

Special Notes:

It appeared that most of the fill displacement and drainage issues were due to excessive seasonal run-off from the carried roadway above. Although the repairs were made to the wall facing and extra drainage relief was installed, it appeared that continued excessive run-off was still occurring due to the displaced stone and clogged weep hole.

Wall Inspection Report

Structure ID#: Southlands Mall - Top Wall

Inspection Date: 2022-07-07

BrM and Element Data Collection

Element # Defect	Element Description	Total Qty	Units	Env. Factor	CS1 Qty	CS2 Qty	CS3 Qty	CS4 Qty
9705	Masonry Wall	7432	SF	1	6928	504	0	0
2310	Leakage			1	0	504	0	0
9750	Retained Material	929	LF	1	929	0	0	0

Element	Description	Element Notes
9705	Masonry Wall	The wall facing was comprised of split-face concrete masonry unit (CMU) blocks that measured 8 in. high by 18 in. long. The wall facing was in good condition. The wall facing included a masonry capstone block for full length at the top of the wall. There were no visible weep holes in the wall facing. (CS2) - Leakage: There was an area of moisture staining emanating between the CMU blocks beginning at Sta. 8+31 continuing to the east end of the wall. An additional area of moisture staining measured 26 ft. in length by 4 courses high beginning at Sta. 7+86. No signs of backfill washout were evident and it appeared runoff was adequately draining at the time of the inspection.
9750	Retained Material	The retained fill was in good condition with no observed areas of backfill loss through the wall facing.

Wall Inspection Report

Structure ID#: Southlands Mall - Top Wall

Inspection Date: 2022-07-07

Maintenance/Repair Recommendations

No maintenance recommendations


Priority Definitions

Priority Level 1 - High (Orange)	Repair within the time specified by the inspector or at most within 30 days
Priority Level 2 - Medium (Yellow)	Repair within 90 days
Priority Level 3 - Low (Green)	Repair within one year or as funding allows

Wall Inspection Report

Structure ID#: Southlands Mall - Top Wall

Inspection Date: 2022-07-07



Overview of Wall on E. Smoky Hill Road

Start of Wall: 39.59912,-104.70885

End of Wall: 39.59803,-104.70605

PHOTO LOG

General Overview	Photo 1	Elevation looking southeast	
Inventory Roadway	Photo 2	Roadway carried looking west	
Inventory Roadway	Photo 3	Roadway carried looking southeast	
Defect	Photo 4	Area of moisture staining on wall facing at Sta. 8+00	
Defect	Photo 5	Area of moisture staining on wall facing at east end	

Southland Walls Inspection - Top Wall - 07/07/2022



Elevation, Looking Southeast



Roadway Carried, Looking West



Roadway Carried, Looking Southeast



Area of Moisture Staining on Wall Facing at Sta. 8+00

Southland Walls Inspection - Top Wall - 07/07/2022



Area of Moisture Staining on Wall Facing at East End



July 13, 2022

WORK ORDER #84958.2

PROPOSAL FOR

NICK MONCADA SPECIAL DISTRICT MANAGEMENT SERVICES SOUTHLANDS METROPOLITAN DISTRICT NO. 1 E. COMMONS AVE. & S. AURORA PARKWAY AURORA, CO 80016

Thank you for allowing us to provide you a quote to perform the work we discussed. We will work out a schedule with you to complete the work once you sign and return this proposal. You may send it via email to service@keesenlandscape.com or fax it to (303) 761-3466. While we do not anticipate any changes to the total cost, Keesen Landscape Management, Inc. does reserve the right to review any proposal that is over 30 days old.

DESCRIPTION OF WORK TO BE PERFORMED

Southlands #1 Planting Improvements

Pricing on this proposal will not exactly match pricing sheet supplied by customer but totals will match.

Renovation of 9 islands on E Smokyhill Rd, S Aurora Parkway, S Main st, Southlands Pkwy and E Common Ave.

Pricing is based on landscape plans L-1 to L-12 and D-1 dated 3/11/22.

Includes labor, equipment and materials as laid out on the plans and scope of work.

We will be substituting Cimarron Granite for the Wyoming Red Granite which is not currently available.

We will be substituting Bearberry for Kinnikinnik.

We will be substituting Stella D'Oro Daylilly for the Yellow Hyperion Daylily

We will be substituting Magnus Coneflower for Rubinstern Coneflower

Pricing assumes static water pressure to all islands within the work area. Irrigation is limited to new valves, drip pipe, emitters, and distribution tubing.

Contract No. - 84958.2

Exclusions

Irrigation controllers, control wire, mainline, boring, sleeving, backflows, stop and waste.

Sale	\$30,762.64
Sales Tax	\$0.00
Total	\$30,762.64

SOUTHLANDS METROPOLITAN DISTRICT NO. 1 WORK ORDER SUMMARY

INCLUDED SERVICES	SALES TAX	TOTAL COST
Island #1 Tree Removal 1 Removal, 4 stumps and 2 topping of dead leaders	\$0.00	\$648.73
Islands #1 Irrigation	\$0.00	\$2,350.00
Run drip line with Mini Root watering with bubbler check. Bubblers are to installed now in preparation of 4 new trees next year.		
Island #2 Tree Removal and Edging 1 dead tree removal	\$0.00	\$752.48
Remove 1 tree from the island. Add 4 sticks of edging.		
Island #2 Irrigation	\$0.00	\$850.00
Run drip line with Mini Root watering with bubbler check. Bubblers are in preparation for replacement of 1 tree and other existing trees that will remain.		
Island #3 Tree Removal and Edging 19 dead tree removal	\$0.00	\$6,804.00
Remove 19 trees from the island. Add 5 sticks of edging.		
Island #3 Irrigation	\$0.00	\$7,300.00
Run drip line with Mini Root watering with bubbler check. Bubblers are in preparation for replacement of 19 trees and other existing trees that will remain.		
Island #4 9 dead Tree Removal	\$0.00	\$3,119.95
Remove 9 trees from the island.		
Island #4 Irrigation	\$0.00	\$7,000.00
Run drip line with Mini Root watering with bubbler check. Bubblers are in		

Contract No 84958.2	Southlands Metropolitan District No. 1		July 13, 2022
preparation for replacement of 9 to	rees and other existing trees that will remain.		
Island #5 Tree Removal 2 dead tr	ees	\$0.00	\$937.48
Remove 2 trees from the island.			
Island #5 Irrigation		\$0.00	\$1,000.00
	ing with bubbler check. Bubblers are in rees and other existing trees that will remain.		
		\$0.00	\$30,762.64

Contract No 84958.2	Southlands Metropolitan District No. 1		July 13, 2022
PAYMENT SCHEDULE			
SCHEDULE	PRICE	SALES TAX	TOTAL PRICE
	\$0.00		
	\$0.00	\$0.00	\$0.00

Note: Unless otherwise specified, supplemental watering is not included in this proposal. If additional watering is necessary to protect plant material warranty, a separate proposal will be submitted.

Note: New plant material will be covered by a 1 year/1 replacement warrant. This does not cover any plant material not connected to working irrigation, owner negligence or circumstances beyond our control including freeze and rodent damage. This includes trees, shrubs and perennial plant material only.

Force Majeure and Delays

Landscape Contractor's installation and warranty obligations under this work order are accepted subject to strikes, labor troubles (including strikes or labor troubles affecting any suppliers of Landscape Contractor), floods, fires, acts of God, accidents, delays, shortages of equipment, contingencies of transportation, and other causes of like or different character beyond the control of the Landscape Contractor. Impossibility of performance by reason of any legislative, executive, or judicial act of any government authority shall excuse performance of or delay in performance of this work order.

Ву

Patrick Atkinson

Date 7/13/2022

Keesen Landscape Management, Inc.

Ву

Date

SPECIAL DISTRICT MANAGEMENT SERVICES

as Agent for

SOUTHLANDS METROPOLITAN DISTRICT NO. 1

Note: Unless otherwise specified in the work order, all required irrigation repairs/modifications will be done at a time and materials rate of \$68.00 per man hour.